

Lot 541/Tract 0273		Items: 15	CH Items: 2	Checklist Inspections: 488
<div><div></div>Anlin Windows</div>				
Code: ZZ_1807				
Category: Windows	Location: Rear Patio		Description: Slider screen missing	Incomplete
Partner: Anlin Windows	Type: Slider door to patio: Screens missing or damaged			
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1813				
Category: Cabinets	Location: Great Room		Description: Install floating shelves Touch up top of cabinet	Incomplete
Partner: Cabinet Connection	Type: Scratches			
<div><div></div>Elia Painting</div>				
Code: ZZ_1805				
Category: Paint	Location: Bedroom 3		Description: Touch up drywall and paint under window, just above baseboard	Incomplete
Partner: Elia Painting	Type: Touch-up required			
<div><div></div>Fenceworks</div>				
Code: ZZ_1811				
Category: Fence	Location: Backyard		Description: Finish fence on north side of home	Incomplete
Partner: Fenceworks	Type: Fence Boards or Posts cracked/warped/defective			
Code: ZZ_1812				
Category: Fence	Location: Front Yard		Description: Gate and north fence need to be installed	CRITICAL Incomplete
Partner: Fenceworks	Type: Gate not installed or has functionality issues			
<div><div></div>G&G Concrete</div>				
Code: ZZ_1808				
Category: Concrete	Location: Backyard		Description: Remove concrete forms at condenser	Incomplete
Partner: G&G Concrete	Type: Slope or other issues with HVAC condenser pad			
<div><div></div>Landscape Connection</div>				

Lot 541/Tract 0273		Items: 15	CH Items: 2	Checklist Inspections: 488
Code: ZZ_1810				
Category: Landscaping	Location: Backyard	Type: Gaps under the fence board - need more dirt to fill in	Description: Fill gap under fence on south side	Incomplete
Partner: Landscape Connection				
<div><div></div>MV Style Electric</div>				
Code: ZZ_1814				
Category: Electrical	Location: Great Room	Type: Light fixture, or pieces of light fixture, are missing	Description: Dome light missing	Incomplete
Partner: MV Style Electric				
Code: ZZ_1815				
Category: Electrical	Location: Front Porch	Type: Light fixture, or pieces of light fixture, are missing	Description: Ring doorbell missing	Incomplete
Partner: MV Style Electric				
Code: ZZ_1817				
Category: Electrical	Location: Bathroom 1	Type: Light fixtures, or pieces of light fixtures, are missing	Description: Finish vanity light installation	Incomplete
Partner: MV Style Electric				
<div><div></div>Quality Plumbing</div>				
Code: ZZ_1806				
Category: Plumbing	Location: Bathroom 3	Type: Hot water not working	Description: Water heater off	CRITICAL Incomplete
Partner: Quality Plumbing				
Code: ZZ_1816				
Category: Plumbing	Location: Kitchen	Type: Garbage disposal not working	Description: Air switch not hooked up	Incomplete
Partner: Quality Plumbing				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: ZZ_1809				
Category: Stucco	Location: Backyard	Type: Inconsistent Fog coat	Description: Touch up under slider back patio	Incomplete
Partner: Tri Valley Plastering & Drywall				

Z Blinds

Code: ZZ_1803			
Category: Window Coverings	Location: Stairwell	Description: Not installed	Incomplete
Partner: Z Blinds	Type: Not installed or not operable		
Code: ZZ_1804			
Category: Window Coverings	Location: Bedroom 4	Description: Shutters missing	Incomplete
Partner: Z Blinds	Type: Not installed or not operable		