
De Young Properties

Lot 15/Tract 6349	Items: 23	CH Items: 1	Checklist Inspections: 259	
Cabinet Connection				
Code: ZZ_1205 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on pantry door	Incomplete	
Code: ZZ_1206 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door above pantry	Incomplete	
Code: ZZ_1207 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door above fridge surround	Incomplete	
Code: ZZ_1208 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door left of hood	Incomplete	
Code: ZZ_1209 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawer right of oven	Incomplete	
Code: ZZ_1213 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Center vanity door has scratches	Incomplete	
Code: ZZ_1214 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on right vanity drawer	Incomplete	

Lot 15/Tract 6349	Items: 23	CH Items: 1	Checklist Inspections: 259
Code: ZZ_1221 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing drawer	Incomplete
Elia Painting			
Code: ZZ_1211 Category: Paint Partner: Elia Painting	Location: Dining Nook Type: Touch-up required	Description: Paint touch up in corner of dining nook	Incomplete
Code: ZZ_1216 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint touch up back wall	Incomplete
Code: ZZ_1217 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint touch up under window	Incomplete
Code: ZZ_1218 Category: Paint Partner: Elia Painting	Location: Den Type: Touch-up required	Description: Paint touch up behind door in den	Incomplete
Code: ZZ_1219 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Paint touch up in corner of bedroom	Incomplete
Code: ZZ_1220 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Remove paint on outlet	Incomplete
Code: ZZ_1223 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Touch up left of light switch	Incomplete



Checklist Lot 15/Tract 6349 Items: 23 CH Items: 1 **Inspections: 259** Code: ZZ_1226 Category: Stucco Location: Exterior Description: Crack in Incomplete corner of back window Partner: Tri Valley Type: Chip/crack/gouge Plastering & Drywall Code: ZZ_1227 Category: Stucco Location: Exterior Description: Fog by back Incomplete yard hosebib Partner: Tri Valley Type: Inconsistent Fog coat Plastering & Drywall