## **De Young Properties**

Lot 18/Tract 6377	Items: 27	CH Items: 2	Checklist Inspections: 368		
Cabinet Connection					
Code: ZZ_1436 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1  Type: Scratches/chips/cracks/gouges in cabinets	Description: Cabinet scratches on right cabinet door	Incomplete		
Code: ZZ_1439  Category: Cabinets  Partner: Cabinet Connection	Location: Bathroom 2  Type: Scratches/chips/cracks/gouges in cabinets	Description: Cabinet scratches on edges of vanity doors	Incomplete		
Code: ZZ_1451 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on faces of doors	Incomplete		
Code: ZZ_1452 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on crown	Incomplete		
Code: ZZ_1454 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Cabinet scratches on left side lowers left of oven	Incomplete		
Code: ZZ_1455 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Crown seam touch up	Incomplete		
Code: ZZ_1456 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Touch up on upper left of microwave	Incomplete		

Lot 18/Tract 6377	Items: 27	CH Items: 2	Checklist Inspections: 368
Code: ZZ_1457  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinet missing trim or other parts	Description: Missing door knobs above microwave	Incomplete
Code: ZZ_1458  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on fridge surround	Incomplete
Elia Painting			
Code: ZZ_1435 Category: Paint Partner: Elia Painting	Location: Bedroom 1  Type: Touch-up required	Description: Paint run on baseboard in master bedroom	Incomplete
Code: ZZ_1440 Category: Paint Partner: Elia Painting	Location: Bathroom 2  Type: Touch-up required	Description: Touch up by baseboard by bathtub	Incomplete
Code: ZZ_1441 Category: Paint Partner: Elia Painting	Location: Bedroom 2  Type: Touch-up required	Description: Paint touch up by base under window	Incomplete
Code: ZZ_1442 Category: Paint Partner: Elia Painting	Location: Bedroom 2  Type: Touch-up required	Description: Paint touch up by base by closet	Incomplete
Code: ZZ_1443  Category: Paint  Partner: Elia  Painting	Location: Bedroom 3  Type: Touch-up required	Description: Paint you up in closet	Incomplete
Code: ZZ_1444  Category: Paint  Partner: Elia  Painting	Location: Bedroom 3  Type: Touch-up required	Description: Paint touch up on wall amright side	Incomplete

Lot 18/Tract 6377	Items: 27	CH Items: 2	Checklist Inspections: 368
Code: ZZ_1445 Category: Paint Partner: Elia Painting	Location: Bedroom 3  Type: Touch-up required	Description: Paint touch up by window	Incomplete
Code: ZZ_1446  Category: Paint  Partner: Elia  Painting	Location: Entryway  Type: Touch-up required	Description: Touch up paint by baseboard	Incomplete
Code: ZZ_1447 Category: Paint Partner: Elia Painting	Location: Dining Nook  Type: Touch-up required	Description: Paint touch up by patio door	Incomplete
Code: ZZ_1448  Category: Paint  Partner: Elia Painting	Location: Great Room  Type: Touch-up required	Description: Paint touch up in corner of great room	Incomplete
Code: ZZ_1450 Category: Paint Partner: Elia Painting	Location: Laundry Room  Type: Touch-up required	Description: Caulking and paint touch up on bottom of baseboard	Incomplete
Fenceworks			
Code: ZZ_1460  Category: Fence  Partner: Fenceworks	Location: Exterior Type: Warped	Description: Trim bottom of gate	Incomplete
Ferguson			
Code: ZZ_1453 Category: Appliances Partner: Ferguson	Location: Kitchen  Type: Appliance(s) missing	Description: Missing	CRITICAL Incomplete
Landscape Connec	ction		

**Checklist Lot 18/Tract 6377** Items: 27 CH Items: 2 **Inspections:** 368 Code: ZZ\_1459 Category: Location: Exterior Description: Landscape CRITICAL Landscaping not completed Incomplete Type: Missing Partner: Landscape Connection **Ohanians Drywall** Code: ZZ\_1434 Location: Bedroom 1 Description: Drywall Category: Drywall missing at corner by Incomplete Type: Drywall texture issues bullnose to master bath Partner: Ohanians Drywall Code: ZZ\_1437 Location: Bathroom 1 Category: Drywall Description: Drywall Incomplete texture by bullnose Type: Drywall texture issues Partner: Ohanians Drywall Code: ZZ\_1438 Location: Bathroom 1 Category: Drywall Description: Drywall Incomplete booger by shower Type: Drywall texture issues Partner: Ohanians Drywall Premier Door Code: ZZ\_1449 Location: Laundry Room Description: Baseboard Category: Millwork damaged at bottom in Incomplete Type: Door trim has chip, gash, gouge, laundry room Partner: Premier cut too short near flooring or is missing

Door