De Young Properties

be roung Propertie	3			
Lot 346/Tract 0273	Items: 32	CH Items: 2	Checklist Inspections: 224	
Anlin Windows				
Code: ZZ_713				
Category: Windows	Location: Great Room Type: Window missing a screen	Description: Missing screens in whole home	Incomplete	
Partner: Anlin Windows				
Cabinet Connection	on			
Code: ZZ_695	Lacation Wholesa	Description: Adjust drawers on island not level	Incomplete	
Category: Cabinets	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted			
Partner: Cabinet Connection				
Code: ZZ_696	Lacation Wholesa			
Category: Cabinets	Location: Kitchen	Description: Adjust doors not level on	Incomplete	
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted	island	•	
Code: ZZ_697	Location: Kitchen	Description, Adjust		
Category: Cabinets	Type: Cabinet drawers and/or doors need	Description: Adjust doors and drawers on hottom cabinets right	Incomplete	
Partner: Cabinet Connection	to be adjusted	bottom cabinets right of oven		
Code: ZZ_698	Location: Kitchen	Description: Adjust		
Category: Cabinets		doors and drawers on bottom cabinets left of oven	Incomplete	
Partner: Cabinet Connection	Type: Cabinet drawers and/or doors need to be adjusted			
Code: ZZ_699	Location: Kitchen			
Category: Cabinets	Type: Cabinet drawers and/or doors need	Description: Adjust doors left of microwave	Incomplete	
Partner: Cabinet Connection	to be adjusted			
Code: ZZ_700				
Category: Cabinets	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Adjust doors right of microwave	Incomplete	
Partner: Cabinet Connection				

Lot 346/Tract 0273	Items: 32	CH Items: 2	Checklist Inspections: 224
Code: ZZ_701 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on crown above microwave	Incomplete
Code: ZZ_702 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Uneven stain on crown left of microwave	Incomplete
Code: ZZ_703 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on doors above fridge	Incomplete
Code: ZZ_704 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Dent on fridge surround	Incomplete
Code: ZZ_705 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Dent on door on island	Incomplete
Code: ZZ_706 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on cabinet doors left of microwave	Incomplete
Code: ZZ_707 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Cabinet door left of microwave missing	Incomplete
Code: ZZ_708 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing cabinet pulls on drawers on island	Incomplete

Lot 346/Tract 0273	Items: 32	CH Items: 2	Checklist Inspections: 224
Code: ZZ_709			
Category: Cabinets	Location: Kitchen	Description: Missing Twe on cabinets in	Incomplete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	kitchen	
Code: ZZ_714	Location: Bathroom 1		
Category: Cabinets	Type: Issues with cabinet drawers and/or	Description: Center vanity drawers are not	Incomplete
Partner: Cabinet Connection	doors functionality	aligned	
Code: ZZ_715	Location: Bathroom 1		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in	Description: Scratches on door face left side vanity	Incomplete
Partner: Cabinet Connection	cabinets		
Code: ZZ_716			
Category: Cabinets	Location: Bathroom 1	Description: Missing Twe	Incomplete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	I WV C	• •
Code: ZZ_718			
Category: Cabinets	Location: Bathroom 2	Description: Missing Twe	Incomplete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	ıwe	
Donald P. Dick			
Code: ZZ_721			
Category: Solar	Location: Garage	Description: Not installed missing inverter	Incomplete
Partner: Donald P. Dick	Type: Installation not complete		
Elia Painting			
Code: ZZ_717			
Category: Paint	Location: Master Closet	Description: Paint touch up attic access	Incomplete
Partner: Elia Painting	Type: Touch-up required		

Checklist Lot 346/Tract 0273 Items: 32 CH Items: 2 Inspections: 224 Code: ZZ_723 Location: Exterior Category: Paint Description: Pop outs Incomplete Type: Stucco pop-out, shutters and/or not painted Partner: Elia deco vents, or fascia paint issues Painting Ferguson Code: ZZ_711 Location: Kitchen Category: Description: No gas to CRITICAL **Appliances** stovetop Incomplete Type: Appliance(s) not operational Partner: Ferguson **G&G** Concrete Code: ZZ_726 Category: Concrete Location: Exterior Description: Side concrete not installed Incomplete Type: Slope issues outside man door Partner: G&G Concrete HSI Code: ZZ_712 Location: Great Room Description: Missing Category: Fire fire sprinkler caps in Incomplete Type: Missing cap for fire sprinkler or cap Sprinklers whole home needs to be pushed up Partner: HSI John Ventresca Co Code: ZZ_722 Category: Stone Location: Exterior Description: Stone for Veneer elevation is being Incomplete Type: Stone veneer missing or damaged installed now Partner: John Ventresca Co Landscape Connection Code: ZZ_725 Location: Exterior Category: Description: Not Landscaping installed Incomplete Type: Missing Partner: Landscape Connection



MV Style Electric

Code: ZZ_724

Category: Electrical

Location: Exterior

Type: Electrical outlets missing or not

functional

Description: Outlet in backyard missing

Incomplete

Partner: MV Style

Electric

Ohanians Drywall

Code: ZZ 720

Category: Drywall

Partner: Ohanians

Drywall

Location: Bedroom 3

Type: Drywall texture issues

Description: Two drywall dots left of

window

Incomplete

Quality Plumbing

Code: ZZ_719

Category: Plumbing

Location: Bathroom 2

Type: Defect(s) in Bath/Shower

fitter/surround

Description: Rust stains

in bath tub

Incomplete

Partner: Quality Plumbing

Visalia Tile

Code: ZZ 710

Category: Tile

Partner: Visalia Tile

Location: Kitchen

Type: Grout at tile is cracked, missing,

wrong color, and/or needs touch-up

Description: Grout crack by fridge

surround

Incomplete