

All Defects		Lot 6/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_2329		Location:	Description: Window in bed 4 won't latch	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2324		Location:	Description: Cabinet touch up in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2333		Location:	Description: Please install twe on either side of the master cabinets	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>California Building Products</div>				
Code: ZZ_2326		Location:	Description: Paint on screen	Incomplete
Category: Fireplace Unit		Type:		
Partner: California Building Products				
<div><div></div>Citadel Roofing and Solar</div>				
Code: ZZ_2336		Location:	Description: Please clean debris off roof.	Incomplete
Category: Roofing		Type:		
Partner: Citadel Roofing and Solar				
<div><div></div>De Young Properties</div>				
Code: ZZ_2337		Location:	Description: Please clean concrete flatwork	Incomplete
Category: Builder Personnel		Type:		
Partner: De Young Properties				
<div><div></div>Elia Painting</div>				

Code: ZZ_2327	Location:		
Category: Paint	Type:	Description: Paint touch up in entry	Incomplete
Partner: Elia Painting			
Code: ZZ_2334	Location:		
Category: Paint	Type:	Description: Bondo sand and paint baseboard in master closet	Incomplete
Partner: Elia Painting			
Code: ZZ_2335	Location:		
Category: Paint	Type:	Description: Paint by landing by linen closet	Incomplete
Partner: Elia Painting			
<div></div> Granite Mountain Stone Design			
Code: ZZ_2332	Location:		
Category: Solid Surface	Type:	Description: Caulk corner of granite in master bathroom	Incomplete
Partner: Granite Mountain Stone Design			
<div></div> Ohanians Drywall			
Code: ZZ_2330	Location:		
Category: Drywall	Type:	Description: Large gap in bed 4 closet by blank plate cover	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2331	Location:		
Category: Drywall	Type:	Description: Drywall line in entry way	Incomplete
Partner: Ohanians Drywall			
<div></div> Quality Plumbing			
Code: ZZ_2328	Location:		
Category: Plumbing	Type:	Description: Broken toilet Handel in bath 3	Incomplete
Partner: Quality Plumbing			
<div></div> Vega Cleanup			

Code: ZZ_2325

Category: Clean Up Interior

Partner: Vega Cleanup

Location:

Type:

Description: Laundry sink is dirty

Incomplete