De Young Properties

All Defects	Lot 34/Tract 6100		
Cabinet Connection			
Code: ZZ_4120 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on faces of both doors in bath 2 vanity Blemishes and thinset on bottom of cabinet	Incomplete
Code: ZZ_4121 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on faces of doors and fridge surround	Incomplete
Code: ZZ_4122 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches to the right of oven on upper and lower cabinets door and drawer faces	Incomplete
Code: ZZ_4123 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on faces of upper and lower cabinets to the left of oven Adjust several doors that are uneven	Incomplete
Code: ZZ_4124 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches and blemishes on cabinet faces on kitchen island	Incomplete
Code: ZZ_4125 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches and blemishes on cabinet faces in master bath. Both left and right vanity	Incomplete