




All Defects		Lot 33/Tract 6100		
<div><div></div>Anlin Windows</div>				
Code: ZZ_4425		Location: Bedroom 2	Description: Adjust window in bed 2 hard to open	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_4406		Location: Bathroom 3	Description: Dent and scratch on door face of vanity in bath 3	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4409		Location: Laundry Room	Description: Chip on cabinet in laundry room door and scratch on false front	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4410		Location: Kitchen	Description: In kitchen all upper right side kitchen doors were drilled wrong	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4411		Location: Kitchen	Description: Please address several crooked door handles in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4412		Location: Kitchen	Description: Left side lower handles in kitchen were drilled wrong	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4413		Location: Kitchen	Description: Scratch on drawer to left of stovetop	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_4414			
Category: Cabinets	Location: Kitchen	Description: Scratch on door face above microwave	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4415			
Category: Cabinets	Location: Kitchen	Description: Scratch on false front on kitchen island	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4416			
Category: Cabinets	Location: Bedroom 1	Description: Side panel of cabinet in master closet is very scratched	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4417			
Category: Cabinets	Location: Bedroom 1	Description: 2 of the inside doors of the cabinet inside the master closet are scratches and different color	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4418			
Category: Cabinets	Location: Bathroom 1	Description: Ding on side panel in master bath cabinets	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_4419			
Category: Cabinets	Location: Bathroom 1	Description: Scratch on false front on right side of master bath cabinets	Incomplete
Partner: Cabinet Connection	Type:		
 Central Valley Overhead Door			
Code: ZZ_4428			
Category: Garage Door	Location: Garage	Description: Garage door opener's are on top of secondary garage door motor	Incomplete
Partner: Central Valley Overhead Door	Type:		

Code: ZZ_4428			
Category: Garage Door	Location: Garage	Description: Garage door opener’s are on top of secondary garage door motor	Incomplete
Partner: Central Valley Overhead Door	Type:		
<div><div></div>Elia Painting</div>			
Code: ZZ_4403			
Category: Paint	Location: Entryway	Description: Paint touch up by baseboard in entry	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4405			
Category: Paint	Location:	Description: Finish paint touch up on trim in whole home	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4424			
Category: Paint	Location: Bathroom 1	Description: Caulk baseboard in master bathroom by tub	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4427			
Category: Paint	Location:	Description: Remove excess paint on hinges in home	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4429			
Category: Paint	Location: Bedroom 1	Description: Paint touch up on trim in master bed	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4430			
Category: Paint	Location:	Description: Paint touch up in upstairs hall on trim	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_4431			
Category: Paint	Location: Stairwell	Description: Paint touch up on trim in stairwell	Incomplete
Partner: Elia Painting	Type:		

All Defects

Lot 33/Tract 6100

Code: ZZ_4432	Location: Bedroom 2		
Category: Paint	Type:	Description: Paint touch up on trim in bed 2	Incomplete
Partner: Elia Painting			
Code: ZZ_4433	Location: Bedroom 3		
Category: Paint	Type:	Description: Paint touch up on trim in bed 3	Incomplete
Partner: Elia Painting			
Code: ZZ_4434	Location: Bedroom 4		
Category: Paint	Type:	Description: Paint touch up on trim in bed 4	Incomplete
Partner: Elia Painting			
Code: ZZ_4435	Location: Bedroom 4		
Category: Paint	Type:	Description: Paint trim around doors by bed 4	Incomplete
Partner: Elia Painting			
Code: ZZ_4436	Location: Great Room		
Category: Paint	Type:	Description: Paint touch up on trim in great room	Incomplete
Partner: Elia Painting			
Code: ZZ_4437	Location: Dining Room		
Category: Paint	Type:	Description: Paint touch up on trim in dining room	Incomplete
Partner: Elia Painting			
Code: ZZ_4438	Location: Flex Super Great Room		
Category: Paint	Type:	Description: Paint touch up on trim in bonus room	Incomplete
Partner: Elia Painting			
 Fresno Shower Door & Mirror			
Code: ZZ_4421	Location: Bathroom 1		
Category: Shower Door & Mirror	Type:	Description: Missing mirror in master bathroom	Incomplete
Partner: Fresno Shower Door & Mirror			
 Granite Mountain Stone Design			

Code: ZZ_4420			
Category: Solid Surface	Location: Bathroom 1	Description: Missing backsplash in master bathroom	Incomplete
Partner: Granite Mountain Stone Design	Type:		
<div><div></div> Ideal Custom Tile</div>			
Code: ZZ_4404			
Category: Tile	Location: Entryway	Description: Grout touch up by tile in entryway	Incomplete
Partner: Ideal Custom Tile	Type:		
Code: ZZ_4426			
Category: Tile	Location: Bathroom 2	Description: Missing tile in bath 2 by toilet	Incomplete
Partner: Ideal Custom Tile	Type:		
<div><div></div> Ohanians Drywall</div>			
Code: ZZ_4407			
Category: Drywall	Location: Bathroom 3	Description: Drywall nail showing in bath 3 above tub	Incomplete
Partner: Ohanians Drywall	Type:		
<div><div></div> Quality Plumbing</div>			
Code: ZZ_4408			
Category: Plumbing	Location:	Description: Chip on toilet seat in bath 3	Incomplete
Partner: Quality Plumbing	Type:		
<div><div></div> Tri Valley Plastering & Drywall</div>			
Code: ZZ_4401			
Category: Stucco	Location:	Description: Fog patches around home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		
Code: ZZ_4402			
Category: Stucco	Location:	Description: Stucco repair in back yard under hose bib	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		

Westech

Code: ZZ_4422	Location: Bathroom 1	Description: Push up can light in master bath	Incomplete
Category: Electrical	Type:		
Partner: Westech			

Code: ZZ_4423	Location: Bathroom 1	Description: Missing plate cover in master bath	Incomplete
Category: Electrical	Type:		
Partner: Westech			