



All Defects		Lot 44/Tract 6164		
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_4107		Location:	Description: Cabinet touch up on cabinet drawers in bath 3	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4113		Location:	Description: Cabinet blemish on master cabinet left vanity Scratches on face of false front	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4114		Location:	Description: Scratches and separation on drawer on right master vanity	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4116		Location:	Description: Scratch on right side of oven surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4117		Location:	Description: Scratches on oven surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div><div>De Young Properties</div></div>				
Code: ZZ_4112		Location:	Description: Nail popping out on trim on pony wall	Incomplete
Category: Builder Personnel		Type:		
Partner: De Young Properties				
<div><div></div><div>Elia Painting</div></div>				
Code: ZZ_4103		Location:	Description: Paint touch up in bonus room	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				

Code: ZZ_4105	Location:	Description: Paint drip on window sill in dining room	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4106	Location:	Description: Paint touch up in bed 4	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4108	Location:	Description: Paint touch up in bath 3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4110	Location:	Description: Paint touch up on pony wall upstairs	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_4111	Location:	Description: Paint touch up in upstairs hall	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div></div> Ferguson			
Code: ZZ_4119	Location:	Description: Missing microwave	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
<div></div> Granite Mountain Stone Design			
Code: ZZ_4115	Location:	Description: Scratches on quartz in bath 2	Incomplete
Category: Solid Surface	Type:		
Partner: Granite Mountain Stone Design			
Code: ZZ_4118	Location:	Description: Scratches on quartz in kitchen	Incomplete
Category: Solid Surface	Type:		
Partner: Granite Mountain Stone Design			

 Ideal Custom Tile

Code: ZZ_4109	Location:		
Category: Tile	Type:	Description: Grout touch up in Harry Potter closet	Incomplete
Partner: Ideal Custom Tile			

 Ohanians Drywall

Code: ZZ_4102	Location:		
Category: Drywall	Type:	Description: Drywall by outlet in bonus room	Incomplete
Partner: Ohanians Drywall			

Code: ZZ_4104	Location:		
Category: Drywall	Type:	Description: Drywall bullnose by slider	Incomplete
Partner: Ohanians Drywall			