

All Defects		Lot 29/Tract 6102		
<div><div></div>Anlin Windows</div>				
Code: ZZ_083		Location:	Description: Screens and slide and glide on all windows	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Everlast Paint</div>				
Code: ZZ_082		Location:	Description: Baseboard in entry	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_084		Location:	Description: Touch up in great room by base	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_085		Location:	Description: Bed 4 paint and caulking touch up	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_086		Location:	Description: Bed the caulking	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_087		Location:	Description: Caulking and paint in master bed and closets	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: ZZ_088		Location:	Description: Fog stucco patches	Incomplete
Category: Stucco		Type:		
Partner: Tri Valley Plastering & Drywall				