

All Defects		Lot 132/Tract 0273		
<div><div></div>Anlin Windows</div>				
Code: ZZ_3457		Location:	Description: Scratches on window frame in bed 3	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
Code: ZZ_3471		Location:	Description: Scratches on trim of slider	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_3464		Location:	Description: Please address cabinet scratches on door faces in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3469		Location:	Description: Please address cabinet scratches on uppers in laundry room	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3476		Location:	Description: Cabinet touch up on fridge surround and on cabinet doors above fridge surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3477		Location:	Description: Cabinet touch up left of oven lower cabinets	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3478		Location:	Description: Please adjust cabinet drawer right of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3479		Location:	Description: Cabinet scratches on doors and drawers on island	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_3484			
Category: Cabinets	Location:	Description: 2 drawers rubbin in master bathroom	Incomplete
Partner: Cabinet Connection	Type:	Address stain on corners of cabinet doors rubbing off	

 Central Valley Overhead Door

Code: ZZ_3488			
Category: Garage Door	Location:	Description: Garage door opener’s are on site	Incomplete
Partner: Central Valley Overhead Door	Type:		

 De Young Properties

Code: ZZ_3463			
Category: Builder Personnel	Location:	Description: Scratches on tub in bath 2	Incomplete
Partner: De Young Properties	Type:		

Code: ZZ_3489			
Category: Builder Personnel	Location:	Description: Gas meter missing	Incomplete
Partner: De Young Properties	Type:		

 Elia Painting

Code: ZZ_3458			
Category: Paint	Location:	Description: Please paint baseboard in bed 2	Incomplete
Partner: Elia Painting	Type:		




Code: ZZ_3468			
Category: Paint	Location:	Description: Please paint door trim to laundry room	Incomplete
Partner: Elia Painting	Type:		

 Fenceworks

Code: ZZ_3490			
Category: Fence	Location:	Description: Finish fence	Incomplete
Partner: Fenceworks	Type:		

 Fresno Shower Door & Mirror

Code: ZZ_3486		Location:	Description: Missing shower enclosure in master bath	Incomplete
Category: Shower Door & Mirror				
Partner: Fresno Shower Door & Mirror				
<div><div></div>Landscape Connection</div>				
Code: ZZ_3491		Location:	Description: Grade backyard	Incomplete
Category: Landscaping				
Partner: Landscape Connection				
<div><div></div>Matthews Quality Construction</div>				
Code: ZZ_3459		Location:	Description: Damaged baseboard in bed 3	Incomplete
Category: Millwork				
Partner: Matthews Quality Construction				
Code: ZZ_3467		Location:	Description: Auto close door to man door not closing	Incomplete
Category: Millwork				
Partner: Matthews Quality Construction				
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_3461		Location:	Description: Texture bullnose in bed 3	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				
Code: ZZ_3466		Location:	Description: Please address drywall in corner of bed 2 bad texture	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				
Code: ZZ_3470		Location:	Description: Drywall line and boogers in coat closet	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				

Code: ZZ_3473	Location:		
Category: Drywall	Type:	Description: Drywall dent by pantry	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3483	Location:		
Category: Drywall	Type:	Description: Drywall booger in master closet	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3487	Location:		
Category: Drywall	Type:	Description: Drywall touch up in garage where holes are cut out	Incomplete
Partner: Ohanians Drywall			
 Simas Flooring & Design			
Code: ZZ_3485	Location:		
Category: Carpet / Hardwood / Laminate	Type:	Description: Missing blinds	Incomplete
Partner: Simas Flooring & Design			
 Visalia Tile			
Code: ZZ_3465	Location:		
Category: Tile	Type:	Description: Fill grout by base by bed 2 and bed 3 doors	Incomplete
Partner: Visalia Tile			
Code: ZZ_3474	Location:		
Category: Tile	Type:	Description: Grout tile by base by fridge surround	Incomplete
Partner: Visalia Tile			
Code: ZZ_3480	Location:		
Category: Tile	Type:	Description: Please grout on either side of island	Incomplete
Partner: Visalia Tile			
 Westech			

All Defects		Lot 132/Tract 0273		
Code: ZZ_3460		Location:		
Category: Electrical		Type:	Description: Missing outlet in bed 3 closet	Incomplete
Partner: Westech				
Code: ZZ_3462		Location:		
Category: Electrical		Type:	Description: Vanity light missing in bath 2	Incomplete
Partner: Westech				
Code: ZZ_3472		Location:		
Category: Electrical		Type:	Description: Missing blank cap for fan prewire in great room	Incomplete
Partner: Westech				
Code: ZZ_3475		Location:		
Category: Electrical		Type:	Description: Missing can light in pantry	Incomplete
Partner: Westech				
Code: ZZ_3481		Location:		
Category: Electrical		Type:	Description: Missing light in master bed	Incomplete
Partner: Westech				
Code: ZZ_3482		Location:		
Category: Electrical		Type:	Description: Missing vanity lights in master bath	Incomplete
Partner: Westech				