De Young Properties

Lot 349/Tract 0273	Items: 37	CH Items: 1	Checklist Inspections: 259
Cabinet Connection			
Code: ZZ_828 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Right upper cabinet door has split right of hood	Incomplete
Code: ZZ_829 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches and dents on lower cabinet door right of oven	Incomplete
Code: ZZ_830 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Ding on right drawer right of oven	Incomplete
Code: ZZ_831 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Blemishes on drawer left of oven	Incomplete
Code: ZZ_832 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Edge of cabinet drawers right of fridge surround paint coming off	Incomplete
Code: ZZ_833 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Adjust doors right of fridge surround	Incomplete

Lot 349/Tract 0273	Items: 37	CH Items: 1	Checklist Inspections: 259
Code: ZZ_834 Category: Cabinets	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on door right vanity	Incomplete
Partner: Cabinet Connection			
Code: ZZ_835 Category: Cabinets	Location: Bathroom 1	December Courter	
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on center drawers	Incomplete
Code: ZZ_836			
Category: Cabinets	Location: Bathroom 1 Type: Cabinet Hardware Issue	Description: Scratch on cabinet pull	Incomplete
Partner: Cabinet Connection	Type: Cabinet Hardware Issue	200e. po	
Code: ZZ_842	Location: Bathroom 3	Description: Scratches on drawers right side of vanity	Incomplete
Category: Cabinets Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_843			
Category: Cabinets	Location: Bathroom 3 Type: Scratches/chips/cracks/gouges in	Description: Scratch on door on right side of	Incomplete
Partner: Cabinet Connection	cabinets	vanity	
Code: ZZ_844			
Category: Cabinets	Location: Bathroom 3 Type: Scratches/chips/cracks/gouges in	Description: Scratch on center depot under sink	Incomplete
Partner: Cabinet Connection	cabinets		
Code: ZZ_849			
Category: Cabinets	Location: Bathroom 2	Description: Address scratches on cabinet drawer right side vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		

Lot 349/Tract 0273	Items: 37	CH Items: 1	Checklist Inspections: 259
Code: ZZ_850 Category: Cabinets Partner: Cabinet	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on right door	Incomplete
Connection Code: ZZ_851 Category: Cabinets	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on center door under sun	Incomplete
Partner: Cabinet Connection			
Code: ZZ_853 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Scratches/chips/cracks/gouges in cabinets	Description: Dent on corner of upper laundry cabinet right door	Incomplete
Code: ZZ_854 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on doors under sink in laundry room	Incomplete
Code: ZZ_855 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on false front under laundry sink	Incomplete
Code: ZZ_856 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on top of dropzone cabinets	Incomplete
Code: ZZ_857 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on lower drop zone cabinet doors	Incomplete

Lot 349/Tract 0273	Items: 37	CH Items: 1	Checklist Inspections: 259
Code: ZZ_840 Category: Drywall Partner: Ohanians Drywall	Location: Hallway Type: Texture issues	Description: Texture under window sill upstairs	Incomplete
Code: ZZ_841 Category: Drywall Partner: Ohanians Drywall	Location: Hallway Type: Texture issues	Description: Texture pony wall by stairwell	Incomplete
Code: ZZ_846 Category: Drywall Partner: Ohanians Drywall	Location: Stairwell Type: Drywall texture issues	Description: Drywall ding in stairwell by landing	Incomplete
Code: ZZ_847 Category: Drywall Partner: Ohanians Drywall	Location: Stairwell Type: Drywall texture issues	Description: 2 drywall dents in stairwell	Incomplete
Premier Door			
Code: ZZ_838 Category: Millwork Partner: Premier Door	Location: Bedroom 3 Type: Door trim has chip, gash, gouge, cut too short near flooring or is missing	Description: Dent on attic access door	Incomplete
Quality Plumbing	J		
Code: ZZ_852 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type: Defect(s) in Bath/Shower fitter/surround	Description: Rust on bottom of tub	Incomplete
Tri Valley Plaster	ring & Drywall		
Code: ZZ_859 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Dent in stucco above gas main	Incomplete

Lot 349/Tract 0273	Items: 37	CH Items: 1	Checklist Inspections: 259
Code: ZZ_860			
Category: Stucco	Location: Exterior	Description: Stucco	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Chip/crack/gouge	touch up around footing base of home	
Code: ZZ_861			
Category: Stucco	Location: Exterior	Description: Stucco hole by back patio outlet	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Chip/crack/gouge		
Code: ZZ_862			
Category: Stucco	Location: Exterior	Description: Stucco hole by slider in back yard	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Chip/crack/gouge		
Code: ZZ_863			
Category: Stucco	Location: Exterior	Description: Fog splotches around home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat		Incomplete