

Lot 13/Tract 6377	Items: 31	CH Items: 4	Checklist Inspections: 236
-------------------	-----------	-------------	----------------------------------

Cabinet Connection

Code: ZZ_1611	Location: Bathroom 1		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on doors right vanity	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1612	Location: Bathroom 1		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on drawers center vanity	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1613	Location: Bathroom 1		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on left vanity panel	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1616	Location: Bathroom 2		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on both doors on vanity	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1617	Location: Bathroom 2		
Category: Cabinets	Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratch on side of door	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1623	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches either side of island	Incomplete
Partner: Cabinet Connection			
Code: ZZ_1624	Location: Kitchen		
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches right side of oven door	Incomplete
Partner: Cabinet Connection			

Code: ZZ_1625	Location: Kitchen	Description: Scratch right side above microwave	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1626	Location: Kitchen	Description: Scratches on drawers left of oven	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1627	Location: Kitchen	Description: Scratches on doors left of microwave	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1628	Location: Kitchen	Description: Scratches on fridge surround panel	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1629	Location: Kitchen	Description: Scratch on crown above fridge surround	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1630	Location: Kitchen	Description: Scratches on doors on island	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1631	Location: Kitchen	Description: Scratches on drawers on island	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			
Code: ZZ_1632	Location: Kitchen	Description: Scratches on false front on island	Incomplete
Category: Cabinets	Type: Cabinets have scratches, chips, and/or cracks		
Partner: Cabinet Connection			

Code: ZZ_1618			
Category: Paint	Location: Bedroom 2	Description: Paint touch up left wall	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1619			
Category: Paint	Location: Bedroom 2	Description: Paint touch up door trim at closet	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1620			
Category: Paint	Location: Bedroom 3	Description: Paint touch up on window sill	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1622			
Category: Paint	Location: Dining Nook	Description: Paint touch up on window sill	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1633			
Category: Paint	Location: Kitchen	Description: Touch up back side of pantry door	Incomplete
Partner: Elia Painting	Type: Touch-up required		
Code: ZZ_1639			
Category: Paint	Location: Exterior	Description: Stucco pop outs need paont	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues		
Code: ZZ_1640			
Category: Paint	Location: Exterior	Description: Front door not painted	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues		
Code: ZZ_1641			
Category: Paint	Location: Exterior	Description: Garage door not painted	Incomplete
Partner: Elia Painting	Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues		

**Lot 13/Tract 6377****Items: 31****CH Items: 4****Checklist  
Inspections:  
236**

Code: ZZ\_1637

Category: Fence

Partner: Fenceworks

Location: Exterior

Type: Warped

Description: Trim  
bottom of gate**Incomplete** Ferguson

Code: ZZ\_1634

Category:  
Appliances

Partner: Ferguson

Location: Kitchen

Type: Appliance(s) missing

Description: Missing

**CRITICAL  
Incomplete** Landscape Connection

Code: ZZ\_1638

Category:  
LandscapingPartner: Landscape  
Connection

Location: Exterior

Type: Missing

Description: Finish  
landscaping**CRITICAL  
Incomplete** Quality Plumbing

Code: ZZ\_1614

Category: Plumbing

Partner: Quality  
Plumbing

Location: Bathroom 1

Type: Hot water not working

Description: No hot  
water**CRITICAL  
Incomplete** Simas Flooring & Design

Code: ZZ\_1621

Category: Carpet /  
Hardwood /  
LaminatePartner: Simas  
Flooring & Design

Location: Bedroom 3

Type: Carpet is not installed

Description: Dirt stain  
on carpet**CRITICAL  
Incomplete** Tri Valley Plastering & Drywall

Code: ZZ_1636			
Category: Stucco	Location: Exterior	Description: Stucco touch up not completed	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Inconsistent Fog coat		

Westech

Code: ZZ_1615			
Category: Electrical	Location: Bedroom 1	Description: Finish electrical outlet in master	Incomplete
Partner: Westech	Type: Electrical outlets missing or not functional		

Code: ZZ_1635			
Category: Electrical	Location: Kitchen	Description: Finish electrical on side of island	Incomplete
Partner: Westech	Type: Electrical outlets missing or not functional		