



All Defects		Lot 39/Tract 6100		
	Cabinet Connection			
Code: ZZ_3321	Location:	Description: Scratches on cabinet faces left and right side in master bathroom	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3337	Location:	Description: Unable to check cabinets in bath 2 due to it being completely taped off	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3341	Location:	Description: Excess grout and drywall on cabinets in kitchen	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3342	Location:	Description: Cabinet scratches on faces of doors and drawers around island	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3343	Location:	Description: Cabinet scratches on uppers and lowers left of oven	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3344	Location:	Description: Discoloration around fridge surround and on upper cabinet doors	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
	De Young Properties			
Code: ZZ_3318	Location:	Description: Paint touch up on ceiling in master closet	Incomplete	
Category: Paint	Type:			
Partner: De Young Properties				
Code: ZZ_3319	Location:	Description: Paint touch up on bullnose in master closet	Incomplete	
Category: Paint	Type:			
Partner: De Young Properties				


Code: ZZ_3323	Location:	Description: Caulk and paint baseboard in master bathroom	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3331	Location:	Description: Paint bullnose in hall	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3332	Location:	Description: Paint corner of laundry room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3334	Location:	Description: Clean up paint on trim around garage door	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
 Elia Painting			
Code: ZZ_3325	Location:	Description: Paint window sill in master bedroom	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3327	Location:	Description: Caulk and paint window sill in dining nook	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3330	Location:	Description: Paint touch up on wall opposite window in great room	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3333	Location:	Description: Paint smudge on door to garage	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3335	Location:	Description: Paint touch up in bath3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Code: ZZ_3339	Location:	Description: Paint touch up on bed 3 closet door	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			


Code: ZZ_3348	Location:	Description: From door not painted	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

 Fenceworks			
---	--	--	--

Code: ZZ_3345	Location:	Description: Fence not installed	Incomplete
Category: Fence	Type:		
Partner: Fenceworks			


 Ferguson			
---	--	--	--

Code: ZZ_3340	Location:	Description: Please install dishwasher	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			

 Ideal Custom Tile			
--	--	--	--

Code: ZZ_3322	Location:	Description: Grout missing in master shower	Incomplete
Category: Tile	Type:		
Partner: Ideal Custom Tile			

Code: ZZ_3328	Location:	Description: Grout tile under dishwasher	Incomplete
Category: Tile	Type:		
Partner: Ideal Custom Tile			

 Landscape Connection			
---	--	--	--

Code: ZZ_3346	Location:	Description: Drainage not installed	Incomplete
Category: Landscaping	Type:		
Partner: Landscape Connection			

Code: ZZ_3347	Location:		
Category: Landscaping	Type:	Description: Front years landscape not installed	Incomplete
Partner: Landscape Connection			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_3320	Location:		
Category: Drywall	Type:	Description: Drywall repair in master closet	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3324	Location:		
Category: Drywall	Type:	Description: Clean excess drywall off of window frame	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3326	Location:		
Category: Drywall	Type:	Description: Clean excess drywall mud off window in dining nook	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3329	Location:		
Category: Drywall	Type:	Description: Clean excess drywall off of window frame in great room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3336	Location:		
Category: Drywall	Type:	Description: Clean up drywall and paint around window frame in bed 2	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3338	Location:		
Category: Drywall	Type:	Description: Clean up drywall around window in bed 3	Incomplete
Partner: Ohanians Drywall			
<div><div></div>Westech</div>			
Code: ZZ_3349	Location:		
Category: Electrical	Type:	Description: Light on front patio not installed	Incomplete
Partner: Westech			