



All Defects		Lot 13/Tract 6260		
<div><div></div>Anlin Windows</div>				
Code: ZZ_887		Location:		
Category: Windows		Type:	Description: Trim on slide not attached	Incomplete
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_883		Location:		
Category: Cabinets		Type:	Description: Scratch on face under cooktop	Incomplete
Partner: Cabinet Connection				
Code: ZZ_890		Location:		
Category: Cabinets		Type:	Description: Scratch on drawer face in master bath Nail holes showing on trim on center vanity in master bath	Incomplete
Partner: Cabinet Connection				
<div><div></div>Everlast Paint</div>				
Code: ZZ_882		Location:		
Category: Paint		Type:	Description: Paint on cabinets in kitchen	Incomplete
Partner: Everlast Paint				
Code: ZZ_885		Location:		
Category: Paint		Type:	Description: Caulk baseboard left of oven in kitchen	Incomplete
Partner: Everlast Paint				
Code: ZZ_886		Location:		
Category: Paint		Type:	Description: Paint around lock on back door	Incomplete
Partner: Everlast Paint				
Code: ZZ_889		Location:		
Category: Paint		Type:	Description: Paint trim and back door in master bed	Incomplete
Partner: Everlast Paint				

All Defects		Lot 13/Tract 6260		
Code: ZZ_892		Location: Type:	Description: Nails showing on baseboard in hall	Incomplete
Category: Paint				
Partner: Everlast Paint				
Code: ZZ_894		Location: Type:	Description: Caulking separating in bed 2 on baseboard	Incomplete
Category: Paint				
Partner: Everlast Paint				
Code: ZZ_895		Location: Type:	Description: Ding on base in hall	Incomplete
Category: Paint				
Partner: Everlast Paint				
	Ohanians Drywall			
Code: ZZ_888		Location: Type:	Description: Hole bubble on ceiling in den	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				
Code: ZZ_891		Location: Type:	Description: Drywall patches in master closet	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				
	Tile Interiors			
Code: ZZ_884		Location: Type:	Description: Grout crack in kitchen by fridge and missing tile by fridge	Incomplete
Category: Tile				
Partner: Tile Interiors				
Code: ZZ_893		Location: Type:	Description: Grout cracks in bath 2 by tub	Incomplete
Category: Tile				
Partner: Tile Interiors				