







| All Defects                 |                    | Lot 33/Tract 6164   |            |  |
|-----------------------------|--------------------|---|------------|--|
| <div><div></div></div>      | Cabinet Connection |   |            |  |
| Code: ZZ_3280               | Location:          | Description: Missing twe in multigen bathroom                               | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3281               | Location:          | Description: Cabinet scratches on drawers in multigen bathroom              | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3283               | Location:          | Description: Scratches on fridge surround in multigen                       | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3285               | Location:          | Description: Missing twe in multigen  | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3286               | Location:          | Description: Cabinet scratches on fronts of doors and drawers in multigen   | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3289               | Location:          | Description: Cabinet scratches all over side of cabinets in kitchen by oven | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3290               | Location:          | Description: Scratches on microwave surround                                | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |
| Code: ZZ_3291               | Location:          | Description: Scratches to right of stovetop uppers and lowers               | Incomplete |  |
| Category: Cabinets          | Type:              |   |            |  |
| Partner: Cabinet Connection |                    |   |            |  |

|                             |           |  |            |
|-----------------------------|-----------|--|------------|
| Code: ZZ_3292               | Location: | Description: Scratches on cabinets uppers and lowers left of oven                              | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3293               | Location: | Description: Cabinet scratches on front of doors and drawers and sides of kitchen island       | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3295               | Location: | Description: Cabinet scratches on laundry cabinet  | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3296               | Location: | Description: Scratches on fridge surround and on cabinets doors left of fridge surround        | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3302               | Location: | Description: Missing all twe   | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3303               | Location: | Description: Cabinet scratches on front of right vanity in bath 3                              | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3306               | Location: | Description: Cabinet scratches on left vanity in bath 3 on fronts of doors and drawers         | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3309               | Location: | Description: Scratches on faces of doors and drawers in bath 2                                 | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |
| Code: ZZ_3313               | Location: | Description: Cabinet scratches on vanity in master bathroom both vanity’s on doors and drawers | Incomplete |
| Category: Cabinets          | Type:     |  |            |
| Partner: Cabinet Connection |           |  |            |

|                        |           |  |            |
|------------------------|-----------|--|------------|
| Code: ZZ_3277          | Location: | Description: Paint window sill in multigen bathroom                | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3288          | Location: | Description: Paint window sills in whole home                      | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3294          | Location: | Description: Paint on side of fridge surround                      | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3299          | Location: | Description: Paint base of stairwell                               | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3301          | Location: | Description: Paint trim in stairwell                               | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3308          | Location: | Description: Paint touch up on wall by closet in bed 3             | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3311          | Location: | Description: Paint touch up on wall under window in master bedroom | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3315          | Location: | Description: Caulk and paint base in master closet                 | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |
| Code: ZZ_3317          | Location: | Description: Paint all exterior doors                              | Incomplete |
| Category: Paint        | Type:     |  |            |
| Partner: Elia Painting |           |  |            |

|  |           |  |            |
|--|-----------|--|------------|
| Code: ZZ_3276  |           |  |            |
| Category: Appliances   | Location: | Description: Missing dishwasher overnight stovetop and microwave | Incomplete |
| Partner: Ferguson  | Type:     |  |            |
| Code: ZZ_3284  |           |  |            |
| Category: Appliances   | Location: | Description: Missing microwave in multigen                       | Incomplete |
| Partner: Ferguson  | Type:     |  |            |
|  Fresno Shower Door & Mirror |           |  |            |
| Code: ZZ_3278  |           |  |            |
| Category: Shower Door & Mirror   | Location: | Description: Missing shower enclosure in multigen bathroom       | Incomplete |
| Partner: Fresno Shower Door & Mirror   | Type:     |  |            |
| Code: ZZ_3282  |           |  |            |
| Category: Shower Door & Mirror   | Location: | Description: Missing mirror in multigen bathroom                 | Incomplete |
| Partner: Fresno Shower Door & Mirror   | Type:     |  |            |
| Code: ZZ_3297  |           |  |            |
| Category: Shower Door & Mirror   | Location: | Description: Missing glass on cabinets                           | Incomplete |
| Partner: Fresno Shower Door & Mirror   | Type:     |  |            |
| Code: ZZ_3300  |           |  |            |
| Category: Shower Door & Mirror   | Location: | Description: Missing all mirrors                                 | Incomplete |
| Partner: Fresno Shower Door & Mirror   | Type:     |  |            |
| Code: ZZ_3304  |           |  |            |
| Category: Shower Door & Mirror   | Location: | Description: Missing shower rod in bath 3                        | Incomplete |
| Partner: Fresno Shower Door & Mirror   | Type:     |  |            |
|  Ideal Custom Tile         |           |  |            |

|  |           |   |            |
|--|-----------|---|------------|
| Code: ZZ_3279  |           |   |            |
| Category: Tile   | Location: | Description: Clean excess grout off shower in multigen          | Incomplete |
| Partner: Ideal Custom Tile   | Type:     |   |            |
| Code: ZZ_3314  |           |   |            |
| Category: Tile   | Location: | Description: Clean excess grout off tile in master shower       | Incomplete |
| Partner: Ideal Custom Tile   | Type:     |   |            |
|  LinkUs                            |           |   |            |
| Code: ZZ_3287  |           |   |            |
| Category: Low Voltage Electrical   | Location: | Description: Terminate data in multigen                         | Incomplete |
| Partner: LinkUs  | Type:     |   |            |
|  Matthews Quality Construction     |           |   |            |
| Code: ZZ_3305  |           |   |            |
| Category: Millwork   | Location: | Description: Missing door stops in whole home                   | Incomplete |
| Partner: Matthews Quality Construction   | Type:     |   |            |
|  Ohanians Drywall                |           |   |            |
| Code: ZZ_3298  |           |   |            |
| Category: Drywall  | Location: | Description: Drywall line by courtyard wall in great room       | Incomplete |
| Partner: Ohanians Drywall  | Type:     |   |            |
| Code: ZZ_3312  |           |   |            |
| Category: Drywall  | Location: | Description: Drywall touch up above light switch in master bath | Incomplete |
| Partner: Ohanians Drywall  | Type:     |   |            |
|  Tri Valley Plastering & Drywall |           |   |            |
| Code: ZZ_3316  |           |   |            |
| Category: Stucco   | Location: | Description: Fog courtyard stucco has staining on it            | Incomplete |
| Partner: Tri Valley Plastering & Drywall   | Type:     |   |            |

Westech

Code: ZZ\_3307

Category: Electrical

Partner: Westech

Location:

Type:

Description: Missing double light plate in bath 3

Incomplete

Code: ZZ\_3310

Category: Electrical

Partner: Westech

Location:

Type:

Description: Missin GB 2 double light plates in bath 2

Incomplete