

All Defects		Lot 40/Tract 6164		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2797		Location:		
Category: Cabinets		Type:	Description: Cabinet touch up in bath 3	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2812		Location:		
Category: Cabinets		Type:	Description: Adjust cabinets in master bath	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2813		Location:		
Category: Cabinets		Type:	Description: Address cabinet scratches in master bath	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2819		Location:		
Category: Cabinets		Type:	Description: Adjust cabinet face in bath 4	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2824		Location:		
Category: Cabinets		Type:	Description: Cabinet touch up in kitchen	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2825		Location:		
Category: Cabinets		Type:	Description: Missing knobs in kitchen	Incomplete
Partner: Cabinet Connection				
Code: ZZ_2831		Location:		
Category: Cabinets		Type:	Description: Align cabinets in laundry room	Incomplete
Partner: Cabinet Connection				
<div><div></div>De Young Properties</div>				
Code: ZZ_2792		Location:		
Category: Paint		Type:	Description: Misc touch up bed 5 closet	Incomplete
Partner: De Young Properties				







Code: ZZ_2795	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 5	Incomplete
Partner: De Young Properties			
Code: ZZ_2796	Location:		
Category: Drywall	Type:	Description: Drywall touch up in bath 3	Incomplete
Partner: De Young Properties			
Code: ZZ_2799	Location:		
Category: Drywall	Type:	Description: Drywall touch up in bath 3 by toilet	Incomplete
Partner: De Young Properties			
Code: ZZ_2801	Location:		
Category: Drywall	Type:	Description: Drywall touch up in bed 4	Incomplete
Partner: De Young Properties			
Code: ZZ_2802	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 4 closet	Incomplete
Partner: De Young Properties			
Code: ZZ_2803	Location:		
Category: Paint	Type:	Description: Paint touch up in hall by bed 5	Incomplete
Partner: De Young Properties			
Code: ZZ_2804	Location:		
Category: Drywall	Type:	Description: Drywall touch up in bed 3	Incomplete
Partner: De Young Properties			
Code: ZZ_2805	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 3	Incomplete
Partner: De Young Properties			
Code: ZZ_2806	Location:		
Category: Paint	Type:	Description: Paint touch up in bed 3	Incomplete
Partner: De Young Properties			

All Defects

Lot 40/Tract 6164

Code: ZZ_2807	Location:	Description: Drywall bullnose touch up in bath 2	Incomplete
Category: Drywall	Type:		
Partner: De Young Properties			
Code: ZZ_2808	Location:	Description: Drywall touch up in bed 2	Incomplete
Category: Drywall	Type:		
Partner: De Young Properties			
Code: ZZ_2809	Location:	Description: Paint touch up in bed 2	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2811	Location:	Description: Paint touch up master bed	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2814	Location:	Description: Paint touch up in master closet	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2815	Location:	Description: Drywall touch up in master bath	Incomplete
Category: Drywall	Type:		
Partner: De Young Properties			
Code: ZZ_2817	Location:	Description: Paint touch up in stairwell	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2818	Location:	Description: Paint touch up in den	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2820	Location:	Description: Paint touch up in bath 4	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			

Code: ZZ_2821	Location:	Description: Drywall touch up in closet under stairs	Incomplete
Category: Drywall	Type:		
Partner: De Young Properties			
Code: ZZ_2822	Location:	Description: Paint touch up under stairs	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2823	Location:	Description: Paint touch up in great room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2828	Location:	Description: Paint touch up in kitchen	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2829	Location:	Description: Paint touch up in bonus room	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_2830	Location:	Description: Drywall touch up in laundry room	Incomplete
Category: Drywall	Type:		
Partner: De Young Properties			
<div></div> Donald P. Dick			
Code: ZZ_2794	Location:	Description: Air vent not installed in bed 5	Incomplete
Category: HVAC	Type:		
Partner: Donald P. Dick			
<div></div> Ferguson			
Code: ZZ_2826	Location:	Description: Missing appliances	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
<div></div> Granite Mountain Stone Design			

All Defects		Lot 40/Tract 6164		
Code: ZZ_2798				
Category: Solid Surface	Location:	Description: Grout by backsplash in bath3	Incomplete	
Partner: Granite Mountain Stone Design	Type:			
 HSI				
Code: ZZ_2827				
Category: Fire Sprinklers	Location:	Description: Fire sprinkler cap not installed in kitchen	Incomplete	
Partner: HSI	Type:			
 Matthews Quality Construction				
Code: ZZ_2816				
Category: Millwork	Location:	Description: Damaged baseboard in master bed	Incomplete	
Partner: Matthews Quality Construction	Type:			
 Ohanians Drywall				
Code: ZZ_2793				
Category: Drywall	Location:	Description: Drywall touch up in bed 5	Incomplete	
Partner: Ohanians Drywall	Type:			
 Quality Plumbing				
Code: ZZ_2810				
Category: Plumbing	Location:	Description: Install washing machine pan in laundry room	Incomplete	
Partner: Quality Plumbing	Type:			
 Simas Flooring & Design				
Code: ZZ_2800				
Category: Carpet / Hardwood / Laminate	Location:	Description: Tuck in carpet in bed 4	Incomplete	
Partner: Simas Flooring & Design	Type:			
 Tri Valley Plastering & Drywall				

Code: ZZ\_2832

Category: Stucco

Partner: Tri Valley Plastering & Drywall

Location:

Type:

Description: Stucco touch up front of home

Incomplete