






All Defects		Lot 60/Tract 6102	
<div><div></div>Anlin Windows</div>			
Code: ZZ_158			
Category: Windows	Location: Great Room	Description: Screen alignment	Incomplete
Partner: Anlin Windows	Type: Window operation	Large slider at backyard patio	
Code: ZZ_159			
Category: Windows	Location: Bedroom 1	Description: Master bedroom right window now locking Scratches on large slider in great room Silicone clean up den left window	Incomplete
Partner: Anlin Windows	Type: Window frame scratched/chipped/dented		
<div><div></div>Cabinet Connection</div>			
Code: ZZ_151			
Category: Cabinets	Location: Kitchen	Description: Various chips and scratches and sticker residue in the kitchen cabinets Also please adjust doors to the right of the fridge area	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_154			
Category: Cabinets	Location: Bathroom 2	Description: Top of cabinets in bath 2 need to be repaired - clumpy staining Various scratches	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_157			
Category: Cabinets	Location:	Description: Check laundry room cabinets	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_160			
Category: Cabinets	Location: Bathroom 1	Description: Master bath cabinets various touch up needed	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
<div><div></div>De Young Properties</div>			

All Defects		Lot 60/Tract 6102		
Code: ZZ_161				
Category: Tile	Location: Bathroom 1	Description: Tile at bath tub and shower in Master bath chipped in several places		Incomplete
Partner: De Young Properties	Type: Tile(s) cracked/chipped			
 Everlast Paint				
Code: ZZ_155				
Category: Paint	Location: Laundry Room	Description: Address caulking at laundry backsplash		Incomplete
Partner: Everlast Paint	Type: Cleanup			
Code: ZZ_163				
Category: Paint	Location: Bedroom 1	Description: Various paint touch up throughout		Incomplete
Partner: Everlast Paint	Type:			
 Fenceworks				
Code: ZZ_162				
Category: Fence	Location: Backyard	Description: Fence posts in several areas Back fence needs skin Gate needs to be replaced		Incomplete
Partner: Fenceworks	Type: Picket(s) split/cracked/incomplete			
 Matthews Quality Construction				
Code: ZZ_152				
Category: Millwork	Location: Bedroom 3	Description: Adjust doors in bedroom 3 closet - not closing flush and door to bed 2 - rubbing at the top		Incomplete
Partner: Matthews Quality Construction	Type:			
 Quality Plumbing				
Code: ZZ_156				
Category: Plumbing	Location: Bathroom 2	Description: Check bath 2 hot water		Incomplete
Partner: Quality Plumbing	Type:			
 Westech				

All Defects		Lot 60/Tract 6102	
Code: ZZ_153	Location: Bedroom 3 Type:	Description: Missing piece from light fixture in bed 3	Incomplete
Category: Electrical			
Partner: Westech			