

All Defects		Lot 131/Tract 0273		
<div><div></div>Anlin Windows</div>				
Code: ZZ_3499		Location:	Description: Master bedroom window hard to open and close	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_3492		Location:	Description: Missing twe right side of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3493		Location:	Description: Missing knobs right side of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3494		Location:	Description: Missing knobs left side of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3495		Location:	Description: Cabinet scratches on bottom cabinets right side of oven on faces	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3496		Location:	Description: Scratches on uppers and on crown either side of microwave	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3497		Location:	Description: Cabinet scratches on cabinet faces right side of fridge surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_3498		Location:	Description: Scratches on crown around fridge	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_3500	Location:	Description: Cabinet scratches on faces of master cabinets	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_3507	Location:	Description: Scratches on faces of cabinets in bath 2	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_3511	Location:	Description: Missing twe in bath 3	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_3512	Location:	Description: Adjust cabinet door on left side of vanity in bath 3	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_3513	Location:	Description: Cabinet scratches on faces of doors and drawers in bath 3	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
<div><div></div>Elia Painting</div>			
Code: ZZ_3506	Location:	Description: Missing caulking in laundry room by baseboard	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_3509	Location:	Description: Paint touch up in stairwell	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div><div></div>Fresno Shower Door & Mirror</div>			
Code: ZZ_3501	Location:	Description: Missing all shower enclosures	Incomplete
Category: Shower Door & Mirror	Type:		
Partner: Fresno Shower Door & Mirror			



Matthews Quality Construction

Code: ZZ_3514

Category: Millwork

Partner: Matthews Quality Construction

Location:

Type:

Description: Install lock on attic access in bed3

Incomplete



Ohanians Drywall

Code: ZZ_3503

Category: Drywall

Partner: Ohanians Drywall

Location:

Type:

Description: Patch drywall hole in garage

Incomplete



Quality Plumbing

Code: ZZ_3504

Category: Plumbing

Partner: Quality Plumbing

Location:

Type:

Description: Start up water heater

Incomplete



Tri Valley Plastering & Drywall

Code: ZZ_3515

Category: Stucco

Partner: Tri Valley Plastering & Drywall

Location:

Type:

Description: Stucco touch up by front door

Incomplete



Visalia Tile

Code: ZZ_3502

Category: Tile

Partner: Visalia Tile

Location:

Type:

Description: One chipped tile in master shower

Incomplete



Westech

Code: ZZ_3505

Category: Electrical

Partner: Westech

Location:

Type:

Description: Light not working in laundry room

Incomplete

Code: ZZ_3508	Location:	Description: Missing vanity light in bath 2	Incomplete
Category: Electrical	Type:		
Partner: Westech			
Code: ZZ_3510	Location:	Description: Missing globe on vanity light in bath 3	Incomplete
Category: Electrical	Type:		
Partner: Westech			