






Lot 536/Tract 0273		Items: 14	CH Items: 4	Checklist Inspections: 0
<div><div></div>Central Valley Rain Gutters</div>				
Code: ZZ_1330				
Category: Rain Gutters	Location: Exterior	Description: Missing rain gutter on right side of garage		Complete
Partner: Central Valley Rain Gutters	Type: Scratches			
<div><div></div>Elia Painting</div>				
Code: ZZ_1322				
Category: Paint	Location: Kitchen	Description: Excess paint on scribe in kitchen		Complete
Partner: Elia Painting	Type: Touch-up required			
<div><div></div>Fenceworks</div>				
Code: ZZ_1329				
Category: Fence	Location: Exterior	Description: Missing gate		Complete
Partner: Fenceworks	Type: Warped			
<div><div></div>Ferguson</div>				
Code: ZZ_1318				
Category: Appliances	Location: Kitchen	Description: Missing oven		CRITICAL Complete
Partner: Ferguson	Type: Appliance(s) missing			
Code: ZZ_1319				
Category: Appliances	Location: Kitchen	Description: Missing microwave		CRITICAL Complete
Partner: Ferguson	Type: Appliance(s) missing			
Code: ZZ_1320				
Category: Appliances	Location: Kitchen	Description: Missing dishwasher		CRITICAL Complete
Partner: Ferguson	Type: Appliance(s) missing			
<div><div></div>G&G Concrete</div>				

Lot 536/Tract 0273		Items: 14	CH Items: 4	Checklist Inspections: 0
Code: ZZ_1324				
Category: Concrete	Location: Exterior		Description: Remove big chunk of concrete by pillar	Complete
Partner: G&G Concrete	Type: Cracks/gouges/chips			
 MV Style Electric				
Code: ZZ_1327				
Category: Electrical	Location: Exterior		Description: Missing doorbell	Complete
Partner: MV Style Electric	Type: Light fixture, or pieces of light fixture, are missing			
 Ohanians Drywall				
Code: ZZ_1317				
Category: Drywall	Location: Bedroom 1		Description: Drywall hole cut in room	Complete
Partner: Ohanians Drywall	Type: Drywall has crack, gash, hole, and/or gouge			
 Quality Plumbing				
Code: ZZ_1323				
Category: Plumbing	Location: Garage		Description: Water heater not working	CRITICAL Complete
Partner: Quality Plumbing	Type: Missing			
Code: ZZ_1325				
Category: Plumbing	Location: Bathroom 2		Description: Clean scratches off tub	Complete
Partner: Quality Plumbing	Type: Fixture needs to be corrected			
 Tri Valley Plastering & Drywall				
Code: ZZ_1328				
Category: Stucco	Location: Exterior		Description: Finish stucco repair on right side of garage	Complete
Partner: Tri Valley Plastering & Drywall	Type: Chip/crack/gouge			
 Visalia Tile				

Lot 536/Tract 0273		Items: 14	CH Items: 4	Checklist Inspections: 0
Code: ZZ_1321	Location: Kitchen		Description: Grout crack by fridge surround	Complete
Category: Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
Partner: Visalia Tile				
Code: ZZ_1326	Location: Entryway		Description: Grout missing by door jambs by bedrooms	Complete
Category: Tile	Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up			
Partner: Visalia Tile				