De Young Properties

Lot 30/Tract 6100	Items: 38	CH Items: 2	Checklist Inspections: 0
Cabinet Connection			
Code: ZZ_476	Location: Bathroom 1		
Category: Cabinets	Type: Issues with cabinet drawers and/or doors	Description: Scratches on drawer on left vanity	Incomplete
Partner: Cabinet Connection	functionality	-	
Code: ZZ_477	Location: Bathroom 1		
Category: Cabinets	Type: Issues with cabinet	Description: Scratches on false front left vanity	Incomplete
Partner: Cabinet Connection	drawers and/or doors functionality	,	
Code: ZZ_478	Location: Bathroom 1	December 5	
Category: Cabinets	Type: Issues with cabinet	Description: Scratches on bottom right drawer on left	Incomplete
Partner: Cabinet Connection	drawers and/or doors functionality	vanity	
Code: ZZ_479	Location: Bathroom 1		
Category: Cabinets	Type: Issues with cabinet drawers and/or doors	Description: Scratches on right drawer on right vanity	Incomplete
Partner: Cabinet Connection	functionality		
Code: ZZ_490	Location: Bathroom 2		
Category: Cabinets	Type: Issues with cabinet drawers and/or doors	Description: Scratches on left drawer	Incomplete
Partner: Cabinet Connection	functionality		
Code: ZZ_491	Location: Bathroom 2		
Category: Cabinets	Type: Issues with cabinet	Description: Scratches on right drawer	Incomplete
Partner: Cabinet Connection	drawers and/or doors functionality	right didwei	
Code: ZZ_497	Location: Kitchen		
Category: Cabinets	Type: Cabinet drawers and/or	Description: Missing uppers left of hood	Incomplete
Partner: Cabinet Connection	doors need to be adjusted	icit of flood	

Lot 30/Tract 6100	Items: 38	CH Items: 2	Checklist Inspections: 0
Code: ZZ_498 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on oven surround	Incomplete
Code: ZZ_499 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Cabinet scratches on drawer under pven	Incomplete
Code: ZZ_500 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on cabinet doors and drawers right of stovetop	Incomplete
Code: ZZ_501 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on door faces under stovetop	Incomplete
Code: ZZ_502 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Door and drawer faces missing left of stovetop	Incomplete
Code: ZZ_503 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches from on corner cabinets	Incomplete
Code: ZZ_504 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on faces to the right of fridge surround	Incomplete
Code: ZZ_505 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Missing handles on uppers right of fridge	Incomplete

Lot 30/Tract 6100	Items: 38	CH Items: 2	Checklist Inspections: 0
Code: ZZ_506 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on doors above fridge	Incomplete
Code: ZZ_507 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on edge of fridge surround	Incomplete
Code: ZZ_508 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on fronts of doors and drawers on island	Incomplete
Elia Painting			
Code: ZZ_480 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Touch-up required	Description: Paint trim in bathroom	Incomplete
Code: ZZ_482 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_483 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_484 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Remove numbers off hindges	Incomplete
Code: ZZ_485 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_486 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Remove numbers off hindges	Incomplete

Lot 30/Tract 6100	Items: 38	CH Items: 2	Checklist Inspections: 0
Code: ZZ_487 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Paint touch up on closet door	Incomplete
Code: ZZ_489 Category: Paint Partner: Elia Painting	Location: Bedroom 4 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_492 Category: Paint Partner: Elia Painting	Location: Bathroom 2 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_493 Category: Paint Partner: Elia Painting	Location: Hallway Type: Touch up	Description: Paint trim	Incomplete
Code: ZZ_494 Category: Paint Partner: Elia Painting	Location: Bathroom 3 Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_495 Category: Paint Partner: Elia Painting	Location: Bathroom 3 Type: Touch-up required	Description: Caulk by baseboard	Incomplete
Code: ZZ_496 Category: Paint Partner: Elia Painting	Location: Great Room Type: Touch-up required	Description: Paint trim	Incomplete
Code: ZZ_512 Category: Paint Partner: Elia Painting	Location: Laundry Room Type: Touch-up required	Description: PInt trim	Incomplete
Code: ZZ_513 Category: Paint Partner: Elia Painting	Location: Exterior Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues	Description: Paint stucco pop outs	Incomplete
Ferguson			

Lot 30/Tract 6100	Items: 38	CH Items: 2	Checklist Inspections: 0
Code: ZZ_510 Category: Appliances Partner: Ferguson	Location: Kitchen Type: Appliance(s) missing	Description: Finish good chase	CRITICAL Incomplete
Ideal Custom Tile			
Code: ZZ_509 Category: Tile Partner: Ideal Custom Tile	Location: Kitchen Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Broken and missing tile toe kick	Incomplete
Matthews Quality Co	nstruction		
Code: ZZ_488 Category: Millwork Partner: Matthews Quality Construction	Location: Bedroom 3 Type: Baseboards missing or have chips/gouges	Description: Damaged baseboard	Incomplete
Code: ZZ_511 Category: Millwork Partner: Matthews Quality Construction	Location: Laundry Room Type: Door trim has chip, gash, gouge, cut too short near flooring or is missing	Description: Door trim damage	Incomplete
Quality Plumbing			
Code: ZZ_481 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type: Missing faucet, shower head, handle, etc	Description: Toilets won't flush because fire sprinklers are not connected	CRITICAL Incomplete