De Young Properties

All Defects	Lot 26/Trac	Lot 26/Tract 6164		
Anlin Windows				
Code: ZZ_1611 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Screens and slide and glide on all windows	Incomplete	
Cabinet Connection				
Code: ZZ_1614 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratch on glade front in laundry room	Incomplete	
Code: ZZ_1618 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratch on left vanity cabinet in master bath	Incomplete	
Code: ZZ_1619 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratch on right vanity cabinets in master bath	Incomplete	
Code: ZZ_1624 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Nail holes on front side of island	Incomplete	
Code: ZZ_1625 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Damaged bottom piece in double cabinet left of stovetop	Incomplete	
Code: ZZ_1626 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Various scratches on cabinets in kitchen	Incomplete	
Citadel Roofing and Solar				

All Defects	Lot 26/Tract 6164		
Code: ZZ_1610 Category: Roofing Partner: Citadel Roofing and Solar	Location: Type:	Description: Remove broken tiles off roof	Incomplete
De Young Properties			
Code: ZZ_1631 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Finish solar set up	Incomplete
Elia Painting			
Code: ZZ_1608 Category: Paint Partner: Elia Painting	Location: Type:	Description: Remove paint on ballisters in stair well	Incomplete
Code: ZZ_1609 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint trim by stairs	Incomplete
Ferguson			
Code: ZZ_1627 Category: Appliances Partner: Ferguson	Location: Type:	Description: Missing appliances	Incomplete
Fresno Shower Door & Mirror			
Code: ZZ_1620 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Master shower enclosure missing	Incomplete
Ideal Custom Tile			
Code: ZZ_1605 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Please fill grout in Harry Potter closet	Incomplete

All Defects	Lot 26/Tract 6164		
LinkUs			
Code: ZZ_1615 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Adhere window contact in master bedroom	Incomplete
Code: ZZ_1617 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Missing window contact in master bathroom	Incomplete
Code: ZZ_1623 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Plate missing in great room for camera pre wire	Incomplete
Code: ZZ_1628 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Finish door contact for garage door	Incomplete
Code: ZZ_1629 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Missing Yale lock and video door bell	Incomplete
Matthews Quality Construction			
Code: ZZ_1604 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Damaged baseboard by stairwell	Incomplete
Code: ZZ_1621 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Missing door knob in bath 3	Incomplete
Code: ZZ_1632 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Adjust garage door spring to automatically close	Incomplete

All Defects	Lot 26/Trac	Lot 26/Tract 6164		
Ohanians Drywall				
Code: ZZ_1606 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Dent in bullnose by bed 4	Incomplete	
Code: ZZ_1607 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Paint and texture on front window sill	Incomplete	
Code: ZZ_1612 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall on pony wall upstairs	Incomplete	
Code: ZZ_1622 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Bullnose in hall to bath 3 dented	Incomplete	
Premier Door				
Code: ZZ_1630 Category: Millwork Partner: Premier Door	Location: Type:	Description: Replace pantry door with plain frosted glass door	Incomplete	
Quality Plumbing				
Code: ZZ_1613 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Finish install of pan in laundry room	Incomplete	
Code: ZZ_1616 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: No hot water in master bath tub	Incomplete	
Tri Valley Plastering & Drywall				

All Defects Lot 26/Tract 6164 Code: ZZ_1633 Location: Category: Stucco Description: Fog by back patio Repair stucco by

Partner: Tri Valley Plastering &

Drywall

side patio Type:

Incomplete