









Lot 530/Tract 0273		Items: 26	CH Items: 8	Checklist Inspections: 0
<div>Cabinet Connection</div>				
Code: ZZ_1371	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing Twe	Complete	
Partner: Cabinet Connection				
Code: ZZ_1372	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing knobs above fridge surround	Complete	
Partner: Cabinet Connection				
Code: ZZ_1373	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing knobs right of oven	Complete	
Partner: Cabinet Connection				
Code: ZZ_1374	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing knobs left of oven	Complete	
Partner: Cabinet Connection				
Code: ZZ_1375	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing knobs on island	Complete	
Partner: Cabinet Connection				
Code: ZZ_1376	Location: Kitchen			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing knobs on all uppers	Complete	
Partner: Cabinet Connection				
Code: ZZ_1385	Location: Bathroom 1			
Category: Cabinets	Type: Cabinet missing trim or other parts	Description: Missing Twe	Complete	
Partner: Cabinet Connection				

Lot 530/Tract 0273		Items: 26	CH Items: 8	Checklist Inspections: 0
Code: ZZ_1388		Location: Bathroom 2	Description: Missing twe	Complete
Category: Cabinets		Type: Cabinet missing trim or other parts		
Partner: Cabinet Connection				
 Central Distributing				
Code: ZZ_1384		Location: Great Room	Description: Finish start up	Complete
Category: Fireplace Unit		Type: Missing parts or all parts not installed		
Partner: Central Distributing				
 Donald P. Dick				
Code: ZZ_1391		Location: Bathroom 2	Description: Missing exhaust fan cover	Complete
Category: HVAC		Type: Exhaust fan is not balanced - too loud		
Partner: Donald P. Dick				
 Elia Painting				
Code: ZZ_1396		Location: Great Room	Description: Paint touch up not completed	Complete
Category: Paint		Type: Touch-up required		
Partner: Elia Painting				
 Ferguson				
Code: ZZ_1377		Location: Kitchen	Description: Missing oven	CRITICAL Complete
Category: Appliances		Type: Appliance(s) missing		
Partner: Ferguson				
Code: ZZ_1378		Location: Kitchen	Description: Missing stovetop	CRITICAL Complete
Category: Appliances		Type: Appliance(s) missing		
Partner: Ferguson				
Code: ZZ_1379		Location: Kitchen	Description: Missing microwave	CRITICAL Complete
Category: Appliances		Type: Appliance(s) missing		
Partner: Ferguson				

Lot 530/Tract 0273		Items: 26	CH Items: 8	Checklist Inspections: 0
Code: ZZ_1380		Location: Kitchen	Description: Missing dishwasher	CRITICAL Complete
Category: Appliances		Type: Appliance(s) missing		
Partner: Ferguson				
Code: ZZ_1381		Location: Kitchen	Description: Missing hood chase	CRITICAL Complete
Category: Appliances		Type: Appliance(s) missing		
Partner: Ferguson				
 Landscape Connection				
Code: ZZ_1395		Location: Exterior	Description: Missing landscaping	CRITICAL Complete
Category: Landscaping		Type: Missing		
Partner: Landscape Connection				
 LinkUs				
Code: ZZ_1382		Location: Great Room	Description: Missing speakers	Complete
Category: Low Voltage Electrical		Type: Low voltage/data jacks missing or not functional		
Partner: LinkUs				
Code: ZZ_1383		Location: Great Room	Description: Missing data and meq	Complete
Category: Low Voltage Electrical		Type: Low voltage/data jacks missing or not functional		
Partner: LinkUs				
Code: ZZ_1387		Location: Bedroom 1	Description: Missing data pre wire	Complete
Category: Low Voltage Electrical		Type: Low voltage/data jacks missing or not functional		
Partner: LinkUs				
Code: ZZ_1393		Location: Bedroom 3	Description: Missing data cable	Complete
Category: Low Voltage Electrical		Type: Low voltage/data jacks missing or not functional		
Partner: LinkUs				
 MV Style Electric				

Code: ZZ_1390	Location: Bathroom 2		
Category: Electrical	Type: Light fixtures, or pieces of light fixtures, are missing	Description: Missing vanity light	Complete
Partner: MV Style Electric			
Code: ZZ_1392	Location: Bedroom 3		
Category: Electrical	Type: Light fixture, or pieces of light fixture, are missing	Description: Missing light	Complete
Partner: MV Style Electric			
Code: ZZ_1394	Location: Bedroom 2		
Category: Electrical	Type: Light fixture, or pieces of light fixture, are missing	Description: Missing light	Complete
Partner: MV Style Electric			
 Quality Plumbing			
Code: ZZ_1386	Location: Bathroom 1		
Category: Plumbing	Type: Missing faucet, shower head, handle, etc	Description: Missing faucets	<div>CRITICAL</div> Complete
Partner: Quality Plumbing			
Code: ZZ_1389	Location: Bathroom 2		
Category: Plumbing	Type: Missing faucet, shower head, handle, etc	Description: Missing faucet	<div>CRITICAL</div> Complete
Partner: Quality Plumbing			