

All Defects		Lot 140/Tract 0273	
<div><div></div></div>	Cabinet Connection		
Code: ZZ_2369 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Dent(s), ding(s), scratch(es)	Description: Bath 2 vanity cabinet: support middle trim inside needs touch up and adjustment - cut too deep - replace Large crack at back panel Nail sticking through from back panel Cut lines too deep for sink at back panel Scratches inside	Incomplete
Code: ZZ_2380 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Fridge surround has some scratches and chils	Incomplete
Code: ZZ_2381 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets to right of fridge area need touch up	Incomplete
Code: ZZ_2382 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Finish exhaust vent surround in cabinet above stove Also touch up needed on sode	Incomplete
Code: ZZ_2383 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets on left side of stove need touch up inside and out Some scratches	Incomplete
Code: ZZ_2384 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets right side of stove have some scratches inside and out - check all blue tape Chip on side of one door	Incomplete
Code: ZZ_2385 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets in island need some touch up	Incomplete

Code: ZZ_2390	Location: Bathroom 1	Description: Master bathroom cabinets need touch up and middle trim piece under both need to be replaced	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_2395	Location: Kitchen	Description: Cabinet trim under counters in kitchen missing	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_2395	Location: Kitchen	Description: Cabinet trim under counters in kitchen need nail holes puttied	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2396	Location: Bathroom 2	Description: Cabinet trim under counter in bath 2 nail holes need putty	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_2397	Location: Bathroom 1	Description: Cabinet trim under counter in bath 1 need putty	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
<div><div></div>Elia Painting</div>			
Code: ZZ_2368	Location: Bedroom 3	Description: Bed 3 needs paint touch up throughout including caulk at window	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2371	Location: Bathroom 2	Description: Finish paint touch up around bath 2 Bubbles around window Baseboard and caulking	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2373	Location: Bedroom 2	Description: Bed 2 - finish paint touch up	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			

Code: ZZ_2379	Location: Kitchen	Description: Paint touch up needed inside the pantry	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_2393	Location: Bedroom 1	Description: Finish paint touch up in master bedroom and bath	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
<div></div> LinkUs			
Code: ZZ_2367	Location: Bedroom 3	Description: Finish data installation termination in bed 3	Incomplete
Category: Low Voltage Electrical	Type:		
Partner: LinkUs			
<div></div> Matthews Quality Construction			
Code: ZZ_2376	Location:	Description: Door handle missing to laundry room	Incomplete
Category: Millwork	Type:		
Partner: Matthews Quality Construction			
<div></div> Ohanians Drywall			
Code: ZZ_2366	Location: Bedroom 3	Description: Bed 3 drywall line in ceiling	Incomplete
Category: Drywall	Type: Crack/gash/ding		
Partner: Ohanians Drywall			
Code: ZZ_2370	Location: Bathroom 2	Description: Bath 2 needs drywall touch up in a few places - next to mirror, wall by shower has crack near base of tub	Incomplete
Category: Drywall	Type: Crack/gash/ding		
Partner: Ohanians Drywall			
Code: ZZ_2372	Location: Bedroom 2	Description: Bed 2 - drywall line in ceiling Couple drywall touch up spots	Incomplete
Category: Drywall	Type: Crack/gash/ding		
Partner: Ohanians Drywall			

All Defects		Lot 140/Tract 0273	
Code: ZZ_2374			
Category: Drywall	Location: Entryway	Description: Drywall touch up needed in entryway and hallway from front door to kitchen and to laundry room Lots of texture issues	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_2375			
Category: Drywall	Location: Laundry Room	Description: Laundry room needs drywall touch up in several places	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_2377			
Category: Drywall	Location: Kitchen	Description: Kitchen needs a lot of drywall touch up - excess texture, cracks and gashes and bullnose pops Check under island as well	Incomplete
Partner: Ohanians Drywall	Type: Texture issue		
Code: ZZ_2378			
Category: Drywall	Location: Kitchen	Description: Pantry needs drywall touch up under shelves and up in ceiling	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_2387			
Category: Drywall	Location: Bedroom 1	Description: Master bedroom needs drywall touch up in a few places including patch by bathroom and bullnose areas	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_2388			
Category: Drywall	Location: Master Closet	Description: Drywall touch up needed in master closet several places	Incomplete
Partner: Ohanians Drywall	Type: Texture issue		
Code: ZZ_2389			
Category: Drywall	Location: Bathroom 1	Description: Drywall touch up needed in master bedroom	Incomplete
Partner: Ohanians Drywall	Type: Texture issue		
Code: ZZ_2394			
Category: Drywall	Location: Great Room	Description: Drywall touch up needed in great room Couple cracks near ceiling Some texture issues	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		

 Visalia Tile

Code: ZZ_2386	Location: Kitchen	Description: Tile by island base needs some grout	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			

Code: ZZ_2392	Location: Bathroom 1	Description: Grout touch up needed in master shower several spots	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			

 Westech

Code: ZZ_2391	Location: Bathroom 1	Description: Right side vanity light missing cover	Incomplete
Category: Electrical	Type:		
Partner: Westech			