De Young Properties

Lot 1/Tract 6377	Items: 8	CH Items: 2	Checklist Inspections: 0
Donald P. Dick			
Code: ZZ_1802 Category: Solar Partner: Donald P. Dick	Location: Exterior Type: Solar panels missing or damaged	Description: Solar finish not complete	CRITICAL Incomplete
Elia Painting			
Code: ZZ_1795 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: TU on north wall	Incomplete
Code: ZZ_1796 Category: Paint Partner: Elia Painting	Location: Entryway Type: Caulking touch-up required at baseboard, window frame, trim/door frame, or wall corners	Description: Hairline crack in corner at entry	Incomplete
Code: ZZ_1798 Category: Paint Partner: Elia Painting	Location: Great Room Type: Touch-up required	Description: Paint tu on south wall at tv/data jack	Incomplete
Code: ZZ_1799 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Few paint tu's on west and north walls	Incomplete
Ferguson			
Code: ZZ_1801 Category: Appliances Partner: Ferguson	Location: Kitchen Type: Appliance(s) missing	Description: Missing microwave	CRITICAL Incomplete
Landscape Connection	n		
Code: ZZ_1800 Category: Landscaping Partner: Landscape Connection	Location: Front Yard Type: Landscape not installed and/or there are dead plants	Description: Install sod	Incomplete

Checklist Lot 1/Tract 6377 Items: 8 CH Items: 2 Inspections: 0 Sunrun Code: ZZ_1797 Location: Garage Description: Solar finish not Category: Solar Incomplete Type: Installation not complete completed

Partner: Sunrun