

Lot 17/Tract 6349	Items: 11	CH Items: 1	Checklist Inspections: 0
-------------------	-----------	-------------	--------------------------

Cabinet Connection

Code: ZZ_921			
Category: Cabinets	Location: Bathroom 1	Description: Scratches on cabinet drawers on right side vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_922			
Category: Cabinets	Location: Bathroom 1	Description: Scratch on door on right side vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_923			
Category: Cabinets	Location: Bathroom 1	Description: Stain blemish on doors on left vanity	Incomplete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets		
Code: ZZ_924			
Category: Cabinets	Location: Bathroom 1	Description: Adjust doors on right side vanity	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality		
Code: ZZ_925			
Category: Cabinets	Location: Bathroom 1	Description: Adjust doors on left side vanity	Incomplete
Partner: Cabinet Connection	Type: Issues with cabinet drawers and/or doors functionality		
Code: ZZ_927			
Category: Cabinets	Location: Master Closet	Description: Scratches on top panel of closet cabinets	Incomplete
Partner: Cabinet Connection	Type: Missing		

Elia Painting

Lot 17/Tract 6349		Items: 11	CH Items: 1	Checklist Inspections: 0
Code: ZZ_928				
Category: Paint	Location: Bedroom 1	Description: Paint touch up by baseboard by master bathroom		Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_929				
Category: Paint	Location: Bedroom 1	Description: Tape line by base please re paint		Incomplete
Partner: Elia Painting	Type: Touch-up required			
Code: ZZ_931				
Category: Paint	Location: Bedroom 2	Description: Paint touch up by baseboard in bed 2		Incomplete
Partner: Elia Painting	Type: Touch-up required			
<div><div></div> HSI</div>				
Code: ZZ_930				
Category: Fire Sprinklers	Location: Bedroom 1	Description: Push up fire sprinkler caps		Incomplete
Partner: HSI	Type: Missing cap for fire sprinkler or cap needs to be pushed up			
<div><div></div> Quality Plumbing</div>				
Code: ZZ_926				
Category: Plumbing	Location: Bathroom 1	Description: Push cap up on rain shower head		CRITICAL Incomplete
Partner: Quality Plumbing	Type: Missing faucet, shower head, handle, etc			