

Lot 356/Tract 0273		Items: 12	CH Items: 0	Checklist Inspections: 291
<div><div></div>Cabinet Connection</div>				
Code: ZZ_957	Location: Kitchen	Description: Missing Twe on island	Incomplete	
Category: Cabinets	Type: Cabinet missing trim or other parts			
Partner: Cabinet Connection				
<div><div></div>Elia Painting</div>				
Code: ZZ_958	Location: Great Room	Description: Paint touch up where drywall was repaired on windows	Incomplete	
Category: Paint	Type: Touch-up required			
Partner: Elia Painting				
Code: ZZ_960	Location: Bathroom 1	Description: Paint drywall touch up in master bath	Incomplete	
Category: Paint	Type: Touch-up required			
Partner: Elia Painting				
Code: ZZ_964	Location: Entryway	Description: Paint touch up	Incomplete	
Category: Paint	Type: Touch-up required			
Partner: Elia Painting				
Code: ZZ_965	Location: Bedroom 1	Description: Paint touch up in master bedroom	Incomplete	
Category: Paint	Type: Touch-up required			
Partner: Elia Painting				
<div><div></div>Fenceworks</div>				
Code: ZZ_966	Location: Exterior	Description: Finish fence	Incomplete	
Category: Fence	Type: Warped			
Partner: Fenceworks				
<div><div></div>MV Style Electric</div>				
Code: ZZ_967	Location: Exterior	Description: Lift up peg box	Incomplete	
Category: Electrical	Type: Electrical outlets missing or not functional			
Partner: MV Style Electric				

Code: ZZ_968	Location: Garage		
Category: Electrical	Type: Electrical outlets missing or not functional	Description: Missing outlet in garage for garage door opener	Incomplete
Partner: MV Style Electric			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_959	Location: Great Room		
Category: Drywall	Type: Drywall texture issues	Description: Clean drywall off fireplace insert	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_961	Location: Laundry Room		
Category: Drywall	Type: Drywall texture issues	Description: Drywall texture issues in laundry room	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_962	Location: Bathroom 2		
Category: Drywall	Type: Drywall texture issues	Description: Drywall gap by tub fitter	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_963	Location: Bedroom 3		
Category: Drywall	Type: Drywall texture issues	Description: Drywall gap around window	Incomplete
Partner: Ohanians Drywall			