

All Defects		Lot 4/Tract 6260		
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_263		Location:		
Category: Cabinets		Type:	Description: Cabinet scratches in kitchen	Incomplete
Partner: Cabinet Connection				
<div><div></div><div>Everlast Paint</div></div>				
Code: ZZ_264		Location:		
Category: Paint		Type:	Description: Paint touch up in great room	Incomplete
Partner: Everlast Paint				
Code: ZZ_266		Location:		
Category: Paint		Type:	Description: Bed 2 touch up	Incomplete
Partner: Everlast Paint				
<div><div></div><div>Ohanians Drywall</div></div>				
Code: ZZ_265		Location:		
Category: Drywall		Type:	Description: Drywall line in master	Incomplete
Partner: Ohanians Drywall				
<div><div></div><div>Quality Plumbing</div></div>				
Code: ZZ_261		Location:		
Category: Plumbing		Type:	Description: Damage to tub in bath 2	Incomplete
Partner: Quality Plumbing				
<div><div></div><div>Tri Valley Plastering & Drywall</div></div>				
Code: ZZ_262		Location:		
Category: Stucco		Type:	Description: Fog courtyard	Incomplete
Partner: Tri Valley Plastering & Drywall				