

All Defects				
<div><div></div>Cabinet Connection</div>				
Code: B_020	Location: Bathroom 1	Description: Cabinet touch up in master bathroom	Incomplete	
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)			
Partner: Cabinet Connection				
Code: B_021	Location: Kitchen	Description: Various kitchen cabinet touch up	Incomplete	
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)			
Partner: Cabinet Connection				
<div><div></div>De Young Properties</div>				
Code: Z_017	Location:	Description: Touch up at upstairs hall outlet	Incomplete	
Category: Drywall	Type: Texture issue			
Partner: De Young Properties				
Code: Z_018	Location: Bedroom 2	Description: Gouge in baseboard	Incomplete	
Category: Millwork	Type:			
Partner: De Young Properties				
Code: ZZ_072	Location:	Description: Gouge in ceiling drywall above staircase	Incomplete	
Category: Drywall	Type: Crack/gash/ding			
Partner: De Young Properties				
Code: Z_014	Location: Entryway	Description: Drywall gouge in entryway	Incomplete	
Category: Drywall	Type: Crack/gash/ding			
Partner: De Young Properties				

All Defects

Code: Z_015

Category: Drywall

Partner: De Young Properties

Location: Entryway

Type: Crack/gash/ding

Description: Drywall gouge in entryway window frame and high up on entryway wall below stair rail. See blue tape

Incomplete

Code: Z_019

Category: Drywall

Partner: De Young Properties

Location:

Type: Texture issue

Description: Texture issues on either side of hall outside of laundry

Incomplete

Code: Z_020

Category: Drywall

Partner: De Young Properties

Location:

Type: Texture issue

Description: Texture issues in upstairs hall

Incomplete

Code: Z_021

Category: Paint

Partner: De Young Properties

Location: Bedroom 1

Type:

Description: Paint touch up and master bedroom. See blue tape

Incomplete

Code: Z_022

Category: Paint

Partner: De Young Properties

Location: Bedroom 1

Type:

Description: Fix caulking in bedroom one closet

Incomplete



Everlast Paint

Code: A_053

Category: Paint

Partner: Everlast Paint

Location: Laundry Room

Type:

Description: Paint touch up on laundry room door

Incomplete



Matthews Quality Construction

Code: J_025

Category: Millwork

Partner: Matthews Quality Construction

Location: Bedroom 1

Type:

Description: Baseboard issue in master bedroom

Incomplete



Tile Interiors

All Defects

Code: G_008	Location: Bathroom 2		
Category: Tile	Type: Grout cracked/missing	Description: Add grout	Incomplete
Partner: Tile Interiors			