

All Defects		Lot 28/Tract 6164		
<div><div></div>California Building Products</div>				
Code: ZZ_2848		Location:		
Category: Fireplace Unit		Type:	Description: Start up fireplace	Incomplete
Partner: California Building Products				
<div><div></div>De Young Properties</div>				
Code: ZZ_2841		Location:		
Category: Builder Personnel		Type:	Description: Clean courtyard	Incomplete
Partner: De Young Properties				
Code: ZZ_2847		Location:		
Category: Builder Personnel		Type:	Description: Clean back patio	Incomplete
Partner: De Young Properties				
<div><div></div>Elia Painting</div>				
Code: ZZ_2835		Location:		
Category: Paint		Type:	Description: Paint touch up in front den	Incomplete
Partner: Elia Painting				
Code: ZZ_2836		Location:		
Category: Paint		Type:	Description: Paint facia on right side of home incomplete	Incomplete
Partner: Elia Painting				
Code: ZZ_2839		Location:		
Category: Paint		Type:	Description: Paint touch up in hall	Incomplete
Partner: Elia Painting				
Code: ZZ_2840		Location:		
Category: Paint		Type:	Description: Paint touch up by outlet in dining room	Incomplete
Partner: Elia Painting				

Code: ZZ_2845	Location:	Description: Paint touch up window sill in dining nook	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_2849	Location:	Description: Paint touch up in den	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_2851	Location:	Description: Paint touch up master bed	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div></div> Ferguson			
Code: ZZ_2843	Location:	Description: Install range	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
Code: ZZ_2844	Location:	Description: Install microwave	Incomplete
Category: Appliances	Type:		
Partner: Ferguson			
<div></div> Fresno Shower Door & Mirror			
Code: ZZ_2852	Location:	Description: Missing shower enclosure	Incomplete
Category: Shower Door & Mirror	Type:		
Partner: Fresno Shower Door & Mirror			
<div></div> Ohanians Drywall			
Code: ZZ_2833	Location:	Description: Drywall repair in bath 2	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			

Code: ZZ_2834	Location:		
Category: Drywall	Type:	Description: Cracks in drywall by entry	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2837	Location:		
Category: Drywall	Type:	Description: Drywall by lot guy switch in bed 2	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2838	Location:		
Category: Drywall	Type:	Description: Drywall touch up by light switch in hall	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2846	Location:		
Category: Drywall	Type:	Description: Drywall touch up in dining nook	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_2850	Location:		
Category: Drywall	Type:	Description: Drywall line in master bed	Incomplete
Partner: Ohanians Drywall			
<div><div></div>Tri Valley Plastering & Drywall</div>			
Code: ZZ_2853	Location:		
Category: Stucco	Type:	Description: Fill hole in stucco by gas main	Incomplete
Partner: Tri Valley Plastering & Drywall			
Code: ZZ_2854	Location:		
Category: Stucco	Type:	Description: Fog exterior	Incomplete
Partner: Tri Valley Plastering & Drywall			
<div><div></div>Vega Cleanup</div>			
Code: ZZ_2842	Location:		
Category: Clean Up Interior	Type:	Description: Clean inside cabinets	Incomplete
Partner: Vega Cleanup			