De Young Properties

Lot 2/Tract 6377	Items: 32	CH Items: 2	Checklist Inspections: 233		
Cabinet Connection					
Code: ZZ_1642 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on right vanity	Incomplete		
Code: ZZ_1643 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on left vanity	Incomplete		
Code: ZZ_1644 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on center drawers	Incomplete		
Code: ZZ_1645 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on Twe	Incomplete		
Code: ZZ_1646 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Adjust drawers on center vanity	Incomplete		
Code: ZZ_1653 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on left door	Incomplete		
Code: ZZ_1654 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on right door	Incomplete		

Lot 2/Tract 6377	Items: 32	CH Items: 2	Checklist Inspections: 233
Code: ZZ_1655 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Issues with cabinet drawers and/or doors functionality	Description: Adjust center doors	Incomplete
Code: ZZ_1664 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on upper cabinets right of microwave	Incomplete
Code: ZZ_1665 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on door above microwave	Incomplete
Code: ZZ_1666 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on doors left of microwave	Incomplete
Code: ZZ_1667 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on lower cabinet doors left of oven	Incomplete
Code: ZZ_1668 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on drawers on island	Incomplete
Code: ZZ_1669 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on doors under island	Incomplete
Code: ZZ_1670 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on false front on island	Incomplete
Elia Painting			

Lot 2/Tract 6377	Items: 32	CH Items: 2	Checklist Inspections: 233
Code: ZZ_1647 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Touch-up required	Description: Paint on trim to master closet door	Incomplete
Code: ZZ_1648 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Touch-up required	Description: Paint touch up on baseboard by shower	Incomplete
Code: ZZ_1649 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Touch-up required	Description: Paint touch up on wall by shower	Incomplete
Code: ZZ_1651 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint touch up on baseboard in master	Incomplete
Code: ZZ_1652 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint on back wall in master	Incomplete
Code: ZZ_1657 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Paint in corner of window	Incomplete
Code: ZZ_1658 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Paint touch up on baseboard right of closet	Incomplete
Code: ZZ_1659 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Touch-up required	Description: Paint touch up on closet doors	Incomplete

Checklist Lot 2/Tract 6377 Items: 32 CH Items: 2 Inspections: 233 Code: ZZ_1663 Location: Stairwell Description: Paint touch Category: Paint up on bullnose at Incomplete Type: Touch-up required bottom Of stairwell Partner: Elia Painting Ferguson Code: ZZ_1671 Location: Kitchen Category: **Description: Missing** CRITICAL **Appliances** appliances Incomplete Type: Appliance(s) missing Partner: Ferguson **G&G** Concrete Code: ZZ_1673 Category: Concrete Location: Exterior Description: Missing Incomplete side garage flatwork Type: Cracks/gouges/chips Partner: G&G Concrete HSI Code: ZZ_1662 Location: Stairwell Description: Missing fire Category: Fire sprinkler cap in Incomplete Type: Missing cap for fire sprinkler or cap Sprinklers stairwell needs to be pushed up Partner: HSI Ideal Custom Tile Code: ZZ_1656 Location: Bathroom 2 Category: Tile Description: Grout Incomplete Type: Grout at tile is cracked, missing, crack by tub Partner: Ideal wrong color, and/or needs touch-up Custom Tile Landscape Connection Code: ZZ_1672 Category: Location: Exterior Description: Landscape CRITICAL Landscaping being installed now Incomplete Type: Missing Partner: Landscape Connection



Ohanians Drywall

Code: ZZ_1650

Category: Drywall

Partner: Ohanians

Drywall

Location: Bathroom 1

Type: Drywall has crack, gash, hole,

and/or gouge

Description: Drywall hole by master shower

Incomplete

Premier Door

Code: ZZ_1660

Category: Millwork

Partner: Premier

Door

Location: Bedroom 3

Type: Missing bypass guide

Description: Missing

bypass glide

Incomplete

Westech

Code: ZZ_1661

Category: Electrical

Location: Stairwell

Type: Light fixture, or pieces of light

fixture, are missing

Partner: Westech

Description: Missing

can lights in stairwell

Incomplete