


All Defects	Lot 125/Tract 0273
-------------	--------------------

 Anlin Windows

Code: ZZ_2175 Category: Windows Partner: Anlin Windows	Location: Bathroom 2 Type: Window operation	Description: Bath 2 - missing screen at window	Incomplete
Code: ZZ_2178 Category: Windows Partner: Anlin Windows	Location: Bedroom 2 Type: Window operation	Description: Bath 2 - missing screen at windows	Incomplete
Code: ZZ_2179 Category: Windows Partner: Anlin Windows	Location: Bedroom 3 Type: Window operation	Description: Bed 3 - missing window screen	Incomplete
Code: ZZ_2182 Category: Windows Partner: Anlin Windows	Location: Great Room Type: Window operation	Description: Great room - both windows to side yard missing screen Right side window doesn't lock	Incomplete
Code: ZZ_2184 Category: Windows Partner: Anlin Windows	Location: Great Room Type: Window operation	Description: Great room - slider screen is missing	Incomplete
Code: ZZ_2185 Category: Windows Partner: Anlin Windows	Location: Dining Nook Type: Window operation	Description: Dining room window is missing a screen	Incomplete
Code: ZZ_2195 Category: Windows Partner: Anlin Windows	Location: Bedroom 1 Type: Window operation	Description: Master bedroom missing screens at all windows	Incomplete
Code: ZZ_2196 Category: Windows Partner: Anlin Windows	Location: Bedroom 1 Type: Window operation	Description: Window from master to backyard doesn't lock properly	Incomplete

All Defects		Lot 125/Tract 0273	
Code: ZZ_2203			
Category: Windows	Location: Bathroom 1	Description: Window at master bath needs screen	Incomplete
Partner: Anlin Windows	Type: Window operation		
 Cabinet Connection			
Code: ZZ_2174			
Category: Cabinets	Location: Bathroom 2	Description: Bath 2 - vanity cabinet - decking under sink needs to be finished	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)	Scratches inside the door Left bottom side has excess material	
Code: ZZ_2187			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets: Left side of cook top - upper corner is rubbing needs to be adjusted. Lower tops of drawers need touch up and inside of left door needs touch up	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2188			
Category: Cabinets	Location: Kitchen	Description: Cabinet above the stove - back of exhaust cover has writing and ceiling of cabinet needs touch up	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2189			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets - side of fridge surround has long lines and staining is off - needs to be corrected	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2190			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets - upper on right side of stove - shelves need touch up, and ceiling of interior of cabinet	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2191			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinet lower right side needs touch up top of drawer and bottom right side inside	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		

All Defects		Lot 125/Tract 0273	
Code: ZZ_2192			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets Adjust uppers above the fridge	Incomplete
Partner: Cabinet Connection	Type: Adjust door(s)		
Code: ZZ_2193			
Category: Cabinets	Location: Kitchen	Description: Kitchen counter need caulking at countertop next to fridge surround	Incomplete
Partner: Cabinet Connection	Type:		
Code: ZZ_2202			
Category: Cabinets	Location: Bathroom 1	Description: Master bath cabinets - left side missing middle trim inside, middle drawers have some scratches, right side middle inside trim is rough - needs finishing	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
<div>Central Valley Overhead Door</div>			
Code: ZZ_2194			
Category: Garage Door	Location: Garage	Description: Missing garage door remotes	Incomplete
Partner: Central Valley Overhead Door	Type:		
<div>Elia Painting</div>			
Code: ZZ_2171			
Category: Paint	Location: Bedroom 3	Description: Bed 3 - Caulk around the window	Incomplete
Partner: Elia Painting	Type: Cleanup		
Code: ZZ_2176			
Category: Paint	Location: Bathroom 2	Description: Bath 2 - caulking needed around window and around the top portion of the shower	Incomplete
Partner: Elia Painting	Type: Cleanup		
Code: ZZ_2180			
Category: Paint	Location: Bedroom 2	Description: Bed 2 - caulk around window	Incomplete
Partner: Elia Painting	Type: Cleanup		

Code: ZZ_2183	Location: Great Room	Description: Great room - caulk corners and around the windows and slider	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2197	Location: Bedroom 1	Description: Master bedroom - caulk corners and around windows	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
<div></div> Fenceworks			
Code: ZZ_2206	Location: Backyard	Description: Finish fence	Incomplete
Category: Fence	Type: Gate string missing/broken		
Partner: Fenceworks			
<div></div> LinkUs			
Code: ZZ_2172	Location: Bedroom 3	Description: Bed 3 - Finish antenna pre-wire in closet	Incomplete
Category: Low Voltage Electrical	Type:		
Partner: LinkUs			
Code: ZZ_2207	Location: Bedroom 3	Description: Install antenna preside and blank plate cover in bedroom 3 closet	Incomplete
Category: Low Voltage Electrical	Type:		
Partner: LinkUs			
Code: ZZ_2208	Location: Bedroom 2	Description: In bed 2 there should be a Data 6 termination - there's a blank plate	Incomplete
Category: Low Voltage Electrical	Type:		
Partner: LinkUs			
<div></div> Ohanians Drywall			
Code: ZZ_2186	Location: Dining Nook	Description: Dining Nook - drywall around outlet needs to be touched up	Incomplete
Category: Drywall	Type: Crack/gash/ding		
Partner: Ohanians Drywall			

Code: ZZ_2198			
Category: Drywall	Location: Bedroom 1	Description: Master bedroom - crack in drywall near right side master bedroom window	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_2205			
Category: Drywall	Location: Bathroom 1	Description: Drywall touch up needed inside water closet of master bath - near light switch	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
<div><div></div>Quality Plumbing</div>			
Code: ZZ_2177			
Category: Plumbing	Location: Bathroom 2	Description: Bath 2 - couple scratches in bath tub	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_2181			
Category: Plumbing	Location: Laundry Room	Description: Laundry room Plumbing clean out has hose bib?	Incomplete
Partner: Quality Plumbing	Type:		
<div><div></div>Tri Valley Plastering & Drywall</div>			
Code: ZZ_2209			
Category: Stucco	Location: Exterior	Description: Fill in stucco at video door bell	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		
Code: ZZ_2211			
Category: Stucco	Location: Exterior	Description: Stucco touch up needed around exterior of home	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Chipped/gouged stucco		
<div><div></div>Visalia Tile</div>			
Code: ZZ_2200			
Category: Tile	Location: Bathroom 1	Description: Master bath - tile touch up needed in shower area - grout is uneven and some tiles have discoloration at edge	Incomplete
Partner: Visalia Tile	Type: Grout cracked/missing		

All Defects		Lot 125/Tract 0273		
Code: ZZ_2201	Location: Bathroom 1	Description: Master bath - tile toe kick needs some grout touch up under vanity sink	Incomplete	
Category: Tile	Type: Grout cracked/missing			
Partner: Visalia Tile				
<div><div></div>Westech</div>				
Code: ZZ_2173	Location: Bathroom 2	Description: Bath 2 - install vanity light	Incomplete	
Category: Electrical	Type:			
Partner: Westech				
Code: ZZ_2199	Location: Bedroom 1	Description: Master bedroom - finish outlet on right side of bed area	Incomplete	
Category: Electrical	Type:			
Partner: Westech				
Code: ZZ_2204	Location: Bathroom 1	Description: Master bath - install vanity lights over sinks	Incomplete	
Category: Electrical	Type:			
Partner: Westech				
Code: ZZ_2210	Location: Garage	Description: Finish outlet in garage	Incomplete	
Category: Electrical	Type:			
Partner: Westech				