De Young Properties

Lot 155/Tract 0273	Items: 15	CH Items: 0	Checklist Inspections: 0
Cabinet Connection			
Code: ZZ_538 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Cabinet missing trim or other parts	Description: Missing Twe	Incomplete
Code: ZZ_539 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Cabinet missing trim or other parts	Description: Missing cabinet knobs	Incomplete
Code: ZZ_540 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Align doors and drawers	Incomplete
Code: ZZ_542 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing twe	Incomplete
Code: ZZ_543 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing handles in whole Kitchen	Incomplete
Code: ZZ_544 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on upper cabinets left of microwave	Incomplete
Code: ZZ_545 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Scratches on doors left of oven	Incomplete

Lot 155/Tract 0273	Items: 15	CH Items: 0	Checklist Inspections: 0
Code: ZZ_546 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Damaged fridge surround	Incomplete
Code: ZZ_549 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing Twe	Incomplete
Code: ZZ_550 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Cabinet missing trim or other parts	Description: Missing handles	Incomplete
Elia Painting			
Code: ZZ_541 Category: Paint Partner: Elia Painting	Location: Great Room Type: Touch-up required	Description: Paint touch up in 7 areas in great room and hall	Incomplete
Code: ZZ_547 Category: Paint Partner: Elia Painting	Location: Hallway Type: Touch up	Description: Touch up paint 6 locations in hallway	Incomplete
Code: ZZ_548 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Touch-up required	Description: Paint touch up on corner	Incomplete
G&G Concrete			
Code: ZZ_551 Category: Concrete Partner: G&G Concrete	Location: Exterior Type: Slope issues	Description: Angled line in concrete flatworm on side yard	Incomplete
Tri Valley Plastering 8	& Drywall		

Lot 155/Tract 0273 Items: 15 CH Items: 0 Checklist Inspections: 0

Code: ZZ_552
Category: Stucco
Partner: Tri Valley
Plastering & Drywall

CH Items: 0

Checklist Inspections: 0

Checklist Inspections: 0

Location: Exterior
Type: Chip/crack/gouge