De Young Properties

| Lot 342/Tract 0273 | Items: 23 | CH Items: 1 | Checklist Inspections: 173 |
|--------------------------------|---------------------|--|----------------------------------|
| Cabinet Connection | | | |
| Code: ZZ_602 | | | |
| Category: Cabinets | Location: Kitchen | Description: Cabinet discoloration and chip in | |
| Partner: Cabinet Connection | Type: Discoloration | face of lower cabinets left of oven | Incomplete |
| Code: ZZ_603 | | | |
| Category: Cabinets | Location: Kitchen | Description: Touch up needed on fridge | Incomplete |
| Partner: Cabinet Connection | Type: Discoloration | surround | Incomplete |
| Code: ZZ_604 | | | |
| Category: Cabinets | Location: Kitchen | Description: Discoloration | Incomplete |
| Partner: Cabinet Connection | Type: Discoloration | on upper cabinet faces left of hood | Incomplete |
| Code: ZZ_605 | | Description, Cabinat | |
| Category: Cabinets | Location: Kitchen | Description: Cabinet scratches dings dents and | Incomplete |
| Partner: Cabinet Connection | Type: Discoloration | miss drilled holes on lower drawers to the right of oven | Incomplete |
| Code: ZZ_606 | | | |
| Category: Cabinets | Location: Kitchen | Description: Discoloration on lower cabinet doors to | Incomplete |
| Partner: Cabinet Connection | Type: Discoloration | the right of oven | Incomplete |
| Code: ZZ_607 | | | |
| Category: Cabinets | Location: Kitchen | Description: Discoloration on lower cabinets to the | Incomplete |
| Partner: Cabinet Connection | Type: Discoloration | left of pantry | incomplete |

Type: Appliance(s) missing

Partner: Ferguson

Checklist Lot 342/Tract 0273 Items: 23 CH Items: 1 Inspections: 173 Code: ZZ_613 Location: Bathroom 2 Category: Plumbing Description: Rust in Incomplete Type: Defect(s) in Bath/Shower bottom of tub fitter/surround Partner: Quality Plumbing Tri Valley Plastering & Drywall Code: ZZ_617 Category: Stucco Location: Exterior Description: Stucco discoloration around Incomplete Partner: Tri Valley Type: Inconsistent Fog coat home Plastering & Drywall Visalia Tile Code: ZZ_600 Location: Kitchen Description: Please Category: Tile address grout crack on Incomplete Type: Grout at tile is cracked, missing, backsplash Partner: Visalia Tile wrong color, and/or needs touch-up Code: ZZ 601 Location: Kitchen Category: Tile Description: Grout Incomplete Type: Grout at tile is cracked, missing, missing by island Partner: Visalia Tile wrong color, and/or needs touch-up Code: ZZ_611 Location: Bathroom 1 Category: Tile Description: Excess grout Incomplete Type: Grout at tile is cracked, missing, on bullnose by shower Partner: Visalia Tile wrong color, and/or needs touch-up