



All Defects		Lot 143/Tract 0273	
<div><div></div>Anlin Windows</div>			
Code: ZZ_2855			
Category: Windows	Location: Bedroom 3	Description: Window in bedroom 3 - left side has excess material preventing window from closing and locking	Incomplete
Partner: Anlin Windows	Type: Window operation		
Code: ZZ_2871			
Category: Windows	Location: Dining Nook	Description: Slider a little difficult to open - slide and glide Window at dining area needs to be adjusted	Incomplete
Partner: Anlin Windows	Type: Window operation		
Code: ZZ_2878			
Category: Windows	Location: Bathroom 1	Description: Missing screen at master bath window	Incomplete
Partner: Anlin Windows	Type: Window operation		
<div><div></div>Cabinet Connection</div>			
Code: ZZ_2856			
Category: Cabinets	Location: Bathroom 2	Description: Bathroom 2 - cabinet middle support is cracked and needs to be replaced Some scratches inside on the left side of cabinet and chip on top of right side door	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2861			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets: fridge upper cabinet needs touch up at crown	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2862			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinet: right side of stove - drawer on right side needs to be adjusted, som scratches and chips on drawers and on shelves in upper cabinet and doors of uppers	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		

All Defects		Lot 143/Tract 0273	
Code: ZZ_2863			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets: above stove - some chips and scratches - doors - inside and out	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2864			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinet: left of stove uppers and lowers have some scratches and chips Check trim under counter too	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2865			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets - island cabinets have scratches and chips inside and out under sink bottom panel is dropping, drawers and doors have lots of gouges Side of island has scratches and gouges under counter	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2866			
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets: Island side facing great room - missing trim under counter Corbels need touch up	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
Code: ZZ_2874			
Category: Cabinets	Location: Bathroom 1	Description: Master bath cabinets - middle support beam change out, drawers need touch up scratches and chips	Incomplete
Partner: Cabinet Connection	Type: Dent(s), ding(s), scratch(es)		
 Elia Painting			
Code: ZZ_2858			
Category: Paint	Location: Bedroom 2	Description: Bed 2: paint touch up needed on the back of the bedroom door in several places	Incomplete
Partner: Elia Painting	Type: Cleanup		
Code: ZZ_2859			
Category: Paint	Location: Entryway	Description: Coat closet needs touch up around door trim And family entry door trim Also bullnose near family entry	Incomplete
Partner: Elia Painting	Type: Cleanup		
Code: ZZ_2860			
Category: Paint	Location: Kitchen	Description: Kitchen paint touch up needed in fridge area and baseboards leading from entry to kitchen	Incomplete
Partner: Elia Painting	Type: Cleanup		

All Defects

Lot 143/Tract 0273

Code: ZZ_2867	Location: Kitchen	Description: Paint touch up needed at island in several spots	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2876	Location: Master Closet	Description: Paint touch up door trim closet	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2877	Location: Bedroom 1	Description: Paint touch up near crown in master bedroom	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
Code: ZZ_2881	Location: Entryway	Description: Touch up caulk at tile next to front door	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
<div></div> Ohanians Drywall			
Code: ZZ_2868	Location: Kitchen	Description: Drywall where counter meets the island needs touch up	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_2872	Location: Great Room	Description: Hole next to fireplace - drywall	Incomplete
Category: Drywall	Type: Crack/gash/ding		
Partner: Ohanians Drywall			
<div></div> Tri Valley Plastering & Drywall			
Code: ZZ_2873	Location: Backyard	Description: Stucco around can lights at patio need to be touch up have gaps	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			

Code: ZZ_2879	Location: Backyard	Description: Stucco over patio is inconsistent-needs to be re dashed	Incomplete
Category: Stucco	Type: Chipped/gouged stucco		
Partner: Tri Valley Plastering & Drywall			
Code: ZZ_2880	Location: Backyard	Description: Touch up thresholds around home	Incomplete
Category: Stucco	Type: Chipped/gouged stucco		
Partner: Tri Valley Plastering & Drywall			
 Visalia Tile			
Code: ZZ_2857	Location: Bathroom 2	Description: Bath 2 - tile touch up needed. Grout for base of bath tub to tile floor skd tile to top of tub, some pencil marks	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			
Code: ZZ_2869	Location: Kitchen	Description: Base of island to tile floor has grout cracks	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			
Code: ZZ_2870	Location: Great Room	Description: Great room needs role touch up in several places. Lots of grout holes near baseboards around the room. One spot of discolored grout. Some pencil marks	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			
Code: ZZ_2875	Location: Bathroom 1	Description: Tile touch up in master shower - excess grout	Incomplete
Category: Tile	Type: Grout cracked/missing		
Partner: Visalia Tile			