

All Defects		Lot 13/Tract 6101	
<div><div></div><div>Elia Painting</div></div>			
Code: ZZ_3134 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type:	Description: Paint touch up bed 3 Closet doors Caulking at window sills with paint Baseboard	Incomplete
Code: ZZ_3136 Category: Paint Partner: Elia Painting	Location: Bathroom 2 Type:	Description: Bathroom 2 caulking at baseboard and paint	Incomplete
Code: ZZ_3139 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Cleanup	Description: Bed 2 baseboard caulking and paint	Incomplete
Code: ZZ_3139 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type:	Description: Bed 2 baseboard caulking and paint - in room and closet	Incomplete
Code: ZZ_3139 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type:	Description: Bed 2 baseboard caulking and paint - in room and closet Bottom of closet door chipped Door trim inside the room needs paint touch up	Incomplete
Code: ZZ_3140 Category: Paint Partner: Elia Painting	Location: Bathroom 2 Type:	Description: Paint touch up - wall by bathroom 2 has green pen mark	Incomplete
Code: ZZ_3143 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type:	Description: Paint touch up at bullnose to master bath Caulking in corners of baseboards	Incomplete
Code: ZZ_3146 Category: Paint Partner: Elia Painting	Location: Master Closet Type:	Description: Paint touch up in master closet Two different products in wall	Incomplete

Code: ZZ_3146	Location: Master Closet	Description: Paint touch up in master closet Two different products in wall Touch up bull noses around home Also corners of baseboards	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div><div></div>G&G Concrete</div>			
Code: ZZ_3148	Location: Backyard	Description: Concrete is discolored or had efflorescence	Incomplete
Category: Concrete	Type:		
Partner: G&G Concrete			
<div><div></div>Matthews Quality Construction</div>			
Code: ZZ_3135	Location: Bathroom 3	Description: Adjust closet doors - not locking in place	Incomplete
Category: Millwork	Type:		
Partner: Matthews Quality Construction			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_3149	Location: Kitchen	Description: Drywall or pain next to fridge area's	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_3149	Location: Kitchen	Description: Drywall or pain next to fridge area's	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
<div><div></div>Quality Plumbing</div>			
Code: ZZ_3133	Location: Laundry Room	Description: Smell of stagnant water in laundry room	Incomplete
Category: Plumbing	Type:		
Partner: Quality Plumbing			

Code: ZZ_3138			
Category: Plumbing	Location: Bathroom 2	Description: Plumbing caulk at sink	Incomplete
Partner: Quality Plumbing	Type:		

Tile Interiors

Code: ZZ_3137			
Category: Tile	Location: Bathroom 2	Description: Grout crack bull nose at water closet in bath 2	Incomplete
Partner: Tile Interiors	Type: Grout cracked/missing		

Code: ZZ_3144			
Category: Tile	Location: Bathroom 1	Description: Tile crack at tile entry to master bath at bullnose	Incomplete
Partner: Tile Interiors	Type:		

Code: ZZ_3145			
Category: Tile	Location: Bathroom 1	Description: Grout cracks in master bath at sink and bull nose to water closet and closet	Incomplete
Partner: Tile Interiors	Type:		

Tri Valley Plastering & Drywall

Code: ZZ_3147			
Category: Stucco	Location: Backyard	Description: Stucco touch up needed at backyard pillar And under thresholds at patio	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		

Vega Cleanup

Code: ZZ_3142			
Category: Clean Up Interior	Location: Kitchen	Description: Kitchen cabinets need hood wipe down inside and ou t	Incomplete
Partner: Vega Cleanup	Type:		

Westech

Code: ZZ_3141			
Category: Electrical	Location: Kitchen	Description: Can light in kitchen not workong	Incomplete
Partner: Westech	Type:		