De Young Properties

All Defects	Lot 30/Trad	ct 6164	
Anlin Windows			
Code: ZZ_1871 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Window in bed 3 springs fell out	Incomplete
Cabinet Connection			
Code: ZZ_1856 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Finish install of twe in kitchen	Incomplete
Code: ZZ_1858 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install 1/4 round in kitchen	Incomplete
Code: ZZ_1859 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install false front in kitchen	Incomplete
Code: ZZ_1860 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Wrong location on DWB in kitchen	Incomplete
Code: ZZ_1866 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust doors and drawers in bath 3 vanity	Incomplete
Code: ZZ_1867 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install twe in bath 3	Incomplete
Code: ZZ_1872 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install twe in bath 2	Incomplete

All Defects	Lot 30/Tract 6164		
Code: ZZ_1877 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Twe missing in master bath cabinets	Incomplete
California Building Products			
Code: ZZ_1854 Category: Fireplace Unit Partner: California Building Products	Location: Type:	Description: Complete fireplace start up	Incomplete
De Young Properties			
Code: ZZ_1849 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Clean debris out of front yard	Incomplete
Code: ZZ_1850 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: No power in home	Incomplete
Code: ZZ_1880 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Missing meters	Incomplete
Donald P. Dick			
Code: ZZ_1862 Category: HVAC Partner: Donald P. Dick	Location: Type:	Description: Install return in super bonus room	Incomplete
Elia Painting			
Code: ZZ_1848 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint trim in whole home	Incomplete

All Defects	Lot 30/Trad	Lot 30/Tract 6164		
Code: ZZ_1864 Category: Paint Partner: Elia Painting	Location: Type:	Description: Trim on stairwell trim	Incomplete	
Code: ZZ_1865 Category: Paint Partner: Elia Painting	Location: Type:	Description: Excess paint on trim upstairs throughout	Incomplete	
Code: ZZ_1870 Category: Paint Partner: Elia Painting	Location: Type:	Description: Finish painting trim upstairs	Incomplete	
Ferguson				
Code: ZZ_1853 Category: Appliances Partner: Ferguson	Location: Type:	Description: Appliances need to be installed	Incomplete	
HSI				
Code: ZZ_1855 Category: Fire Sprinklers Partner: HSI	Location: Type:	Description: Push up fire sprinkler in great room	Incomplete	
Ideal Custom Tile				
Code: ZZ_1873 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Replace tile in bath 2 shower and finish corner in bath 2 shower	Incomplete	
Code: ZZ_1876 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Finish install of shower drain in master shower	Incomplete	
Code: ZZ_1878 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Cracked and missing tile in master shower	Incomplete	

All Defects	Lot 30/Trac	et 6164	
Ohanians Drywall			
Code: ZZ_1861 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Re install drywall in kitchen where hood vent was cut out	Incomplete
Code: ZZ_1863 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall on window ledge in great room has divot in it	Incomplete
Code: ZZ_1869 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Hole in drywall in bath 3	Incomplete
Quality Plumbing			
Code: ZZ_1851 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: No water to home	Incomplete
Code: ZZ_1852 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Incorrect toilet seat in powder bath	Incomplete
Code: ZZ_1868 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Finish install of drain in bath 3	Incomplete
Code: ZZ_1875 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Please finish install of standing tub in master bath	Incomplete
Code: ZZ_1879 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Missing air button in kitchen	Incomplete
Tri Valley Plastering & Drywall			

All Defects	Lot 30/Trac	t 6164	
Code: ZZ_1847 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco crack on front patio ceiling	Incomplete
Westech Code: ZZ_1857 Category: Electrical Partner: Westech	Location: Type:	Description: Finish electrical in kitchen	Incomplete
Code: ZZ_1874 Category: Electrical Partner: Westech	Location: Type:	Description: Finish outlet in master bed	Incomplete