De Young Properties

be roung rroperties				
Lot 151/Tract 0273	Items: 38	CH Items: 4	Checklist Inspections: 271	
Anlin Windows				
Code: J_088 Category: Windows Partner: Anlin Windows	Location: Great Room Type: Window lock is not installed and/or is not working	Description: Left window springs popped out	CRITICAL Incomplete	
Code: J_089 Category: Windows Partner: Anlin Windows	Location: Great Room Type: Window lock is not installed and/or is not working	Description: Right window latch not locking	CRITICAL Incomplete	
Code: J_094 Category: Windows Partner: Anlin Windows	Location: Bedroom 1 Type: Window lock is not installed and/or is not working	Description: Window hard to open	CRITICAL Incomplete	
Cabinet Connection	on			
Code: B_114 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Missing Twe under island	Incomplete	
Code: B_115 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Scratch on face of cabinet door to the left of hood	Incomplete	
Code: B_116 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet missing trim or other parts	Description: Cabinet touch up happening	Incomplete	
Code: B_117 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Left side of vanity has stains touch up needed	Incomplete	

Lot 151/Tract 0273	Items: 38	CH Items: 4	Checklist Inspections: 271
Code: B_118 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Right side vanity doors need touch up on corners	Incomplete
Code: B_119 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Cabinet touch up is happening now	Incomplete
Elia Painting			
Code: A_149 Category: Paint Partner: Elia Painting	Location: Hallway Type: Touch up	Description: Paint touch up in hall by cut out	Incomplete
Code: A_150 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint touch up under window in master	Incomplete
Code: A_151 Category: Paint Partner: Elia Painting	Location: Bedroom 1 Type: Touch-up required	Description: Paint needed where drywall booger was under window in master	Incomplete
Code: A_152 Category: Paint Partner: Elia Painting	Location: Garage Type: If finished - touch-up required	Description: Ding on garage door	Incomplete
Code: A_153 Category: Paint Partner: Elia Painting	Location: Exterior Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues	Description: Paint front door and man door	Incomplete
Fenceworks			

Checklist Lot 151/Tract 0273 Items: 38 CH Items: 4 Inspections: **271** Code: F_023 Location: Exterior Description: Replace Category: Fence one 2x4 on left side Incomplete Type: Warped yard mildew Partner: Fenceworks Ferguson Code: J_090 Location: Kitchen Category: **Description: Missing** CRITICAL **Appliances** stovetop Incomplete Type: Appliance(s) missing Partner: Ferguson Code: J_091 Location: Kitchen **Description: Missing** Category: CRITICAL **Appliances** Incomplete oven Type: Appliance(s) missing Partner: Ferguson Code: J 092 Location: Kitchen Category: **Description: Missing** CRITICAL **Appliances** microwave Incomplete Type: Appliance(s) missing Partner: Ferguson Code: J 093 Location: Kitchen Description: Missing Category: CRITICAL **Appliances** dishwasher Incomplete Type: Appliance(s) missing Partner: Ferguson Landscape Connection Code: J 096 Category: Location: Exterior Description: Landscape CRITICAL Landscaping dug up Incomplete Type: Missing Partner: Landscape Connection MV Style Electric Code: J 087 Location: Bathroom 2 Category: Electrical Description: Light Incomplete Type: Light fixtures, or pieces of light fixture is upside down Partner: MV Style fixtures, are missing Electric

Checklist Lot 151/Tract 0273 Items: 38 CH Items: 4 Inspections: 271 Code: D_013 Location: Exterior Category: Plumbing **Description: Plumbing** Incomplete line clogged Type: Missing Partner: Quality Plumbing Tri Valley Plastering & Drywall Code: F_016 Category: Stucco Location: Exterior Description: Touch up Incomplete under patio brick Partner: Tri Valley Type: Chip/crack/gouge Plastering & Drywall Code: F_017 Category: Stucco Location: Exterior Description: Wires on Incomplete left side of home Partner: Tri Valley Type: Chip/crack/gouge Plastering & Drywall Code: F_018 Location: Exterior Category: Stucco Description: Touch up Incomplete on front pop outs Partner: Tri Valley Type: Chip/crack/gouge Plastering & Drywall Code: F 019 Category: Stucco Location: Exterior **Description: Wires** showing on right side of Incomplete Partner: Tri Valley Type: Chip/crack/gouge home Plastering & Drywall Code: F 020 Category: Stucco Location: Exterior Description: Hole in stucco on right side of Incomplete Partner: Tri Valley Type: Chip/crack/gouge home Plastering & Drywall Code: F_021 Category: Stucco Location: Exterior Description: Outlet covers up on back side Incomplete Partner: Tri Valley Type: Chip/crack/gouge of home Plastering & Drywall

Checklist Lot 151/Tract 0273 Items: 38 CH Items: 4 Inspections: 27İ Code: F_022 Category: Stucco Location: Exterior Description: Stucco touch up on forging Incomplete Partner: Tri Valley Type: Chip/crack/gouge back of home Plastering & Drywall Visalia Tile Code: E_019 Location: Laundry Room Description: Grout Category: Tile missing in laundry room Incomplete Type: Grout at tile is cracked, missing, by dryer vent wrong color, and/or needs touch-up Partner: Visalia Tile Code: E_020 Location: Bathroom 1 Description: Marks on Category: Tile Incomplete tile by shower Type: Pencil marks on tile Partner: Visalia Tile