

All Defects		Lot 9/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_2751		Location:	Description: Missing window latch in bed 4	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2756		Location:	Description: Cabinet touch up bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2757		Location:	Description: Cabinet touch up in master bathroom right vanity	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2758		Location:	Description: Adjust cabinet drawers on right vanity in master bathroom	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2759		Location:	Description: Cabinet touch up on left vanity in master bathroom	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2760		Location:	Description: Replace door on left vanity in master bathroom	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2764		Location:	Description: Replace 2 cabinet drawer faces in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2765		Location:	Description: Missing knobs above hood in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_2766	Location:	Description: Missing knobs on cabinet doors under kitchen sink	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			

 De Young Properties

Code: ZZ_2762	Location:	Description: Clean back patio	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			

Code: ZZ_2763	Location:	Description: Clean courtyard	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			

 Elia Painting

Code: ZZ_2753	Location:	Description: Paint touch up in hall by banister	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Code: ZZ_2754	Location:	Description: Paint on cabinets in laundry room	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Code: ZZ_2755	Location:	Description: Paint on cabinets in bath 3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

Code: ZZ_2770	Location:	Description: Caulk trim by tile in bath 4	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			

 Ideal Custom Tile

Code: ZZ_2761	Location:	Description: Install drain in master shower	Incomplete
Category: Tile	Type:		
Partner: Ideal Custom Tile			

Ohanians Drywall

Code: ZZ_2752	Location:	Description: Drywall touch up on window sill in bed 4	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			

Tri Valley Plastering & Drywall

Code: ZZ_2750	Location:	Description: Stucco touch up by front door	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			

Code: ZZ_2767	Location:	Description: Fill gaps at footing on either side of garage door	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			

Code: ZZ_2768	Location:	Description: Touch up stucco by footing in back yard	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			

Code: ZZ_2769	Location:	Description: Stucco fog white paint on stucco front of home	Incomplete
Category: Stucco	Type:		
Partner: Tri Valley Plastering & Drywall			