

Lot 5/Tract 0001	Defects: 1	CH Defects: 1	Checklist Inspections: 8
------------------	------------	---------------	--------------------------

G&G Concrete

Code: ZZ_022	Location: Backyard	Description: CH test	CRITICAL Incomplete
Category: Concrete	Type: Crack		
Partner: G&G Concrete			