

All Defects		Lot 17/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_1570		Location:	Description: Slide and glide on all windows and install screens	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
Code: ZZ_1578		Location:	Description: Bent window frame in master bedroom	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1564		Location:	Description: Install twe on all cabinets	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1565		Location:	Description: Adjust all cabinet faces in bath 2 are rubbing	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1566		Location:	Description: Cabinet scratch in laundry vanity	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1572		Location:	Description: Address cabinet scratches in kitchen in various locations and install hood box	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1576		Location:	Description: Adjust drawers and address scratches in master bath drawers are hard to open and scrape	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>Elia Painting</div>				

Code: ZZ_1556	Location:		
Category: Paint	Type:	Description: Paint back side of front door	Incomplete
Partner: Elia Painting			
Code: ZZ_1557	Location:		
Category: Paint	Type:	Description: Paint entry on right side	Incomplete
Partner: Elia Painting			
Code: ZZ_1558	Location:		
Category: Paint	Type:	Description: Paint bullnose by bed 2	Incomplete
Partner: Elia Painting			
Code: ZZ_1560	Location:		
Category: Paint	Type:	Description: Paint several areas in bed 2 and bed 2 closet	Incomplete
Partner: Elia Painting			
Code: ZZ_1561	Location:		
Category: Paint	Type:	Description: Paint scratch in closet of bed 3 paint drip above door in bed 3	Incomplete
Partner: Elia Painting			
Code: ZZ_1562	Location:		
Category: Paint	Type:	Description: Caulk baseboard in bath 2 behind toilet	Incomplete
Partner: Elia Painting			
Code: ZZ_1569	Location:		
Category: Paint	Type:	Description: Various touch up in bed 2	Incomplete
Partner: Elia Painting			
Code: ZZ_1571	Location:		
Category: Paint	Type:	Description: Paint window sill by courtyard	Incomplete
Partner: Elia Painting			
Code: ZZ_1574	Location:		
Category: Paint	Type:	Description: Various paint touch ups in great room by media center	Incomplete
Partner: Elia Painting			

Code: ZZ_1575	Location:	Description: Paint areas in master bed and fix baseboard under window	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
<div><div></div><div>Fresno Shower Door & Mirror</div></div>			
Code: ZZ_1577	Location:	Description: Finish installation of shower door in master bath	Incomplete
Category: Shower Door & Mirror	Type:		
Partner: Fresno Shower Door & Mirror			
<div><div></div><div>Ideal Custom Tile</div></div>			
Code: ZZ_1563	Location:	Description: Grout crack by bath 2 tub	Incomplete
Category: Tile	Type:		
Partner: Ideal Custom Tile			
<div><div></div><div>Ohanians Drywall</div></div>			
Code: ZZ_1559	Location:	Description: Drywall and paint by outlet in bed 2	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_1567	Location:	Description: Drywall line in laundry room	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
<div><div></div><div>Quality Plumbing</div></div>			
Code: ZZ_1568	Location:	Description: Install sinks in bathrooms	Incomplete
Category: Plumbing	Type:		
Partner: Quality Plumbing			
<div><div></div><div>Simas Flooring & Design</div></div>			

All Defects		Lot 17/Tract 6164	
Code: ZZ_1573			
Category: Carpet / Hardwood / Laminate	Location:	Description: Remove stain on carpet	Incomplete
Partner: Simas Flooring & Design	Type:		
<div><div></div>Tri Valley Plastering & Drywall</div>			
Code: ZZ_1579			
Category: Stucco	Location:	Description: Address stucco footing in courtyard	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		
Code: ZZ_1580			
Category: Stucco	Location:	Description: Stucco footing around home and by backyard hose bib	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:		