

Lot 541/Tract 0273		Items: 15	CH Items: 2	Checklist Inspections: 488
<div><div></div>Anlin Windows</div>				
<div><div>Code: ZZ_1807</div><div>Category: Windows</div><div>Partner: Anlin Windows</div></div> <div><div>Location: Rear Patio</div><div>Type: Slider door to patio: Screens missing or damaged</div></div> <div><div>Description: Slider screen missing</div><div>Incomplete</div></div>				
<div><div></div>Cabinet Connection</div>				
<div><div>Code: ZZ_1813</div><div>Category: Cabinets</div><div>Partner: Cabinet Connection</div></div> <div><div>Location: Great Room</div><div>Type: Scratches</div></div> <div><div>Description: Install floating shelves Touch up top of cabinet</div><div>Incomplete</div></div>				
<div><div></div>Elia Painting</div>				
<div><div>Code: ZZ_1805</div><div>Category: Paint</div><div>Partner: Elia Painting</div></div> <div><div>Location: Bedroom 3</div><div>Type: Touch-up required</div></div> <div><div>Description: Touch up drywall and paint under window, just above baseboard</div><div>Incomplete</div></div>				
<div><div></div>Fenceworks</div>				
<div><div>Code: ZZ_1811</div><div>Category: Fence</div><div>Partner: Fenceworks</div></div> <div><div>Location: Backyard</div><div>Type: Fence Boards or Posts cracked/warped/defective</div></div> <div><div>Description: Finish fence on north side of home</div><div>Incomplete</div></div>				
<div><div>Code: ZZ_1812</div><div>Category: Fence</div><div>Partner: Fenceworks</div></div> <div><div>Location: Front Yard</div><div>Type: Gate not installed or has functionality issues</div></div> <div><div>Description: Gate and north fence need to be installed</div><div><div>CRITICAL</div>Incomplete</div></div>				
<div><div></div>G&G Concrete</div>				
<div><div>Code: ZZ_1808</div><div>Category: Concrete</div><div>Partner: G&G Concrete</div></div> <div><div>Location: Backyard</div><div>Type: Slope or other issues with HVAC condenser pad</div></div> <div><div>Description: Remove concrete forms at condenser</div><div>Incomplete</div></div>				
<div><div></div>Landscape Connection</div>				

Lot 541/Tract 0273		Items: 15	CH Items: 2	Checklist Inspections: 488
Code: ZZ_1810				
Category: Landscaping	Location: Backyard	Type: Gaps under the fence board - need more dirt to fill in	Description: Fill gap under fence on south side	Incomplete
Partner: Landscape Connection				
<div><div></div>MV Style Electric</div>				
Code: ZZ_1814				
Category: Electrical	Location: Great Room	Type: Light fixture, or pieces of light fixture, are missing	Description: Dome light missing	Incomplete
Partner: MV Style Electric				
Code: ZZ_1815				
Category: Electrical	Location: Front Porch	Type: Light fixture, or pieces of light fixture, are missing	Description: Ring doorbell missing	Incomplete
Partner: MV Style Electric				
Code: ZZ_1817				
Category: Electrical	Location: Bathroom 1	Type: Light fixtures, or pieces of light fixtures, are missing	Description: Finish vanity light installation	Incomplete
Partner: MV Style Electric				
<div><div></div>Quality Plumbing</div>				
Code: ZZ_1806				
Category: Plumbing	Location: Bathroom 3	Type: Hot water not working	Description: Water heater off	CRITICAL Incomplete
Partner: Quality Plumbing				
Code: ZZ_1816				
Category: Plumbing	Location: Kitchen	Type: Garbage disposal not working	Description: Air switch not hooked up	Incomplete
Partner: Quality Plumbing				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: ZZ_1809				
Category: Stucco	Location: Backyard	Type: Inconsistent Fog coat	Description: Touch up under slider back patio	Incomplete
Partner: Tri Valley Plastering & Drywall				

 Z Blinds

Code: ZZ_1803				
Category: Window Coverings	Location: Stairwell		Description: Not installed	Incomplete
	Type: Not installed or not operable			
Partner: Z Blinds				
Code: ZZ_1804				
Category: Window Coverings	Location: Bedroom 4		Description: Shutters missing	Incomplete
	Type: Not installed or not operable			
Partner: Z Blinds				