

| | | | |
|--------------------|-----------|-------------|----------------------------------|
| Lot 156/Tract 0273 | Items: 20 | CH Items: 1 | Checklist Inspections: 222 |
|--------------------|-----------|-------------|----------------------------------|

Anlin Windows

| | | | |
|------------------------|--|--|--------------------------------|
| Code: Z_011 | | | |
| Category: Windows | Location: Bedroom 3 | Description: Window latch not working on right window in bedroom | <div>CRITICAL</div> Incomplete |
| Partner: Anlin Windows | Type: Window lock is not installed and/or is not working | | |

| | | | |
|------------------------|------------------------|---|------------|
| Code: ZZ_640 | | | |
| Category: Windows | Location: Dining Nook | Description: Window frame coming apart in dining nook | Incomplete |
| Partner: Anlin Windows | Type: Window operation | | |

Cabinet Connection

| | | | |
|-----------------------------|---|--|------------|
| Code: ZZ_631 | | | |
| Category: Cabinets | Location: Kitchen | Description: Scratches on cabinet door faces to the right side of oven | Incomplete |
| Partner: Cabinet Connection | Type: Cabinets have scratches, chips, and/or cracks | | |

| | | | |
|-----------------------------|---|--|------------|
| Code: ZZ_632 | | | |
| Category: Cabinets | Location: Kitchen | Description: Cabinet scratches on door faces for upper cabinets right of microwave | Incomplete |
| Partner: Cabinet Connection | Type: Cabinets have scratches, chips, and/or cracks | | |

| | | | |
|-----------------------------|---|---|------------|
| Code: ZZ_633 | | | |
| Category: Cabinets | Location: Kitchen | Description: Scratches around fridge surround | Incomplete |
| Partner: Cabinet Connection | Type: Cabinets have scratches, chips, and/or cracks | | |

| | | | |
|-----------------------------|---|---|------------|
| Code: ZZ_634 | | | |
| Category: Cabinets | Location: Kitchen | Description: Scratches on false front on island | Incomplete |
| Partner: Cabinet Connection | Type: Cabinets have scratches, chips, and/or cracks | | |

| | | | |
|------------------------------|---|--|------------|
| Code: ZZ_635 | Location: Bathroom 1 | | |
| Category: Cabinets | Type: Scratches/chips/cracks/gouges in cabinets | Description: Scratches on right vanity doors | Incomplete |
| Partner: Cabinet Connection | | | |
| Code: ZZ_636 | Location: Bathroom 1 | | |
| Category: Cabinets | Type: Scratches/chips/cracks/gouges in cabinets | Description: Scratches on left vanity doors | Incomplete |
| Partner: Cabinet Connection | | | |
| Code: ZZ_637 | Location: Bathroom 1 | | |
| Category: Cabinets | Type: Scratches/chips/cracks/gouges in cabinets | Description: Drawers scratches | Incomplete |
| Partner: Cabinet Connection | | | |
| Code: ZZ_638 | Location: Bathroom 2 | | |
| Category: Cabinets | Type: Scratches/chips/cracks/gouges in cabinets | Description: Scratches on cabinet door faces | Incomplete |
| Partner: Cabinet Connection | | | |
| <div></div> Fenceworks | | | |
| Code: ZZ_639 | Location: Exterior | | |
| Category: Fence | Type: Warped | Description: Fence not complete | Incomplete |
| Partner: Fenceworks | | | |
| <div></div> Ohanians Drywall | | | |
| Code: C_120 | Location: Bedroom 2 | | |
| Category: Drywall | Type: Drywall has crack, gash, hole, and/or gouge | Description: Drywall crack in corner of room revers bullnose | Incomplete |
| Partner: Ohanians Drywall | | | |
| <div></div> Quality Plumbing | | | |
| Code: Z_010 | Location: Bathroom 2 | | |
| Category: Plumbing | Type: Defect(s) in Bath/Shower fitter/surround | Description: Please address bottom of tub has rust stains | Incomplete |
| Partner: Quality Plumbing | | | |



Tri Valley Plastering & Drywall

Code: F_041

Category: Stucco

Location: Exterior

Partner: Tri Valley
Plastering & Drywall

Type: Chip/crack/gouge

Description: Stucco holes
and patches in front
entry

Incomplete

Code: F_042

Category: Stucco

Location: Exterior

Partner: Tri Valley
Plastering & Drywall

Type: Chip/crack/gouge

Description: Repair
stucco under address
box

Incomplete

Code: F_043

Category: Stucco

Location: Exterior

Partner: Tri Valley
Plastering & Drywall

Type: Chip/crack/gouge

Description: Stucco holes
left of home

Incomplete

Code: F_044

Category: Stucco

Location: Exterior

Partner: Tri Valley
Plastering & Drywall

Type: Chip/crack/gouge

Description: Stucco
patches on back patio

Incomplete



Visalia Tile

Code: E_035

Category: Tile

Location: Bathroom 1

Partner: Visalia Tile

Type: Pencil marks on tile

Description: Pencil marks
on tile in shower

Incomplete

Code: E_036

Category: Tile

Location: Hallway

Partner: Visalia Tile

Type: Crack or chipped tile

Description: Pencil marks
on tile in hall by bath 2

Incomplete

Code: E_037

Category: Tile

Location: Bathroom 2

Partner: Visalia Tile

Type: Pencil marks on tile

Description: Pencil marks
on tile by toilet

Incomplete