

All Defects		Lot 5/Tract 6102		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_125		Location: Kitchen		
Category: Cabinets		Type: Dent(s), ding(s), scratch(es)	Description: Various scratches on cabinets in kitchen See blue tape areas	Incomplete
Partner: Cabinet Connection				
<div><div></div>Tile Interiors</div>				
Code: ZZ_126		Location: Bathroom 1		
Category: Tile		Type: Tile(s) not flush	Description: Master bath tile surround needs to be redone Looks bad Please addressed	Incomplete
Partner: Tile Interiors				
Code: ZZ_126		Location: Bathroom 1		
Category: Tile		Type:	Description: Master bath tile surround needs to be redone Looks bad Please addressed	Incomplete
Partner: Tile Interiors				