

All Defects		Lot 13/Tract 6164	
<div><div></div>Citadel Roofing and Solar</div>			
Code: ZZ_2041	Location: Exterior	Description: Inspect roof for missing and broken roof tiles and remove any debris	Incomplete
Category: Roofing	Type: Cracked/broken/chipped roof tile(s)		
Partner: Citadel Roofing and Solar			
<div><div></div>De Young Properties</div>			
Code: ZZ_2043	Location:	Description: Bed 3 closet top shelf has rough edge. Please hot mud or wood filler to patch and smooth area them then re paint	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			
<div><div></div>Elia Painting</div>			
Code: ZZ_2045	Location: Bedroom 3	Description: Please paint side of bed 3 closet shelf where dings are	Incomplete
Category: Paint	Type: Chip/gouge/scratch		
Partner: Elia Painting			
Code: ZZ_2048	Location: Bedroom 3	Description: Cut line above baseboard in bed 3 and bed 3 closet	Incomplete
Category: Paint	Type: Cleanup		
Partner: Elia Painting			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_2042	Location: Bathroom 3	Description: Drywall repair on window sill in bed 3	Incomplete
Category: Drywall	Type: Texture issue		
Partner: Ohanians Drywall			
Code: ZZ_2044	Location: Bedroom 3	Description: Drywall by can light in bed 3 closet has drywall flaking on one corner of can light	Incomplete
Category: Drywall	Type: Texture issue		
Partner: Ohanians Drywall			

All Defects		Lot 13/Tract 6164		
Code: ZZ_2046				
Category: Drywall	Location: Bedroom 3	Description: Drywall lines in bed 3 closet by door		Incomplete
Partner: Ohanians Drywall	Type: Texture issue			
Code: ZZ_2047				
Category: Drywall	Location: Bedroom 3	Description: Two drywall areas in bed 3 back wall by outlet		Incomplete
Partner: Ohanians Drywall	Type: Texture issue			