

All Defects		Lot 34/Tract 6180	
<div><div></div></div>	Cabinet Connection		
Code: B_022	Location: Bathroom 1	Description: Cabinet touch-up master bath	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: B_023	Location: Bathroom 2	Description: Touch up and bath 2	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: B_024	Location: Laundry Room	Description: Fix open hole at base of laundry cabinet	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: B_025	Location: Multi-Gen Kitchenette	Description: Finish piece at base of multi gen kitchenette	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: B_026	Location: Kitchen	Description: Various cabinet touch-up throughout kitchen	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: B_027	Location: Kitchen	Description: Cabinet filler piece missing at base to the right of cooktop for tile to attach to	Incomplete
Category: Cabinets	Type: Part missing		
Partner: Cabinet Connection			
<div><div></div></div>	Central Valley Overhead Door		

All Defects		Lot 34/Tract 6180		
Code: J_027				
Category: Garage Door	Location: Garage	Description: Garage door won't close all the way. Seems sensors might be out of alignment	Incomplete	
Partner: Central Valley Overhead Door	Type: Door operation			
De Young Properties				
Code: Z_023				
Category: Paint	Location: Bedroom 2	Description: Various paint touch-ups	Incomplete	
Partner: De Young Properties	Type:			
Code: Z_024				
Category: Carpet / Hardwood / Laminate	Location: Stairwell			
Partner: De Young Properties	Type:	Description: Baseboard touch up at top of stair well	Incomplete	
Code: Z_025				
Category: Drywall	Location: Bedroom 3			
Partner: De Young Properties	Type: Texture issue			
Code: Z_026				
Category: Paint	Location: Stairwell	Description: There is touch up in stairwell	Incomplete	
Partner: De Young Properties	Type:			
Code: Z_027				
Category: Paint	Location: Bathroom 3			
Partner: De Young Properties	Type:	Description: Various touch up	Incomplete	
G&G Concrete				
Code: J_029				
Category: Concrete	Location: Exterior			
Partner: G&G Concrete	Type:	Description: Various concrete flat work issue(s)	Incomplete	
John Ventresca Co				

All Defects		Lot 34/Tract 6180		
Code: J_026				
Category: Fireplace Surround		Location: Great Room	Description: Various grout touch up	Incomplete
		Type: Mortar cracked/missing		
Partner: John Ventresca Co				
<div><div></div>Landscape Connection</div>				
Code: J_030				
Category: Rain Gutters		Location: Exterior	Description: Extend PVC downspout connection at front right corner of home	Incomplete
Partner: Landscape Connection		Type:		
<div><div></div>Tile Interiors</div>				
Code: G_009				
Category: Tile		Location: Kitchen	Description: Various tile issues in kitchen	Incomplete
Partner: Tile Interiors		Type:		
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: E_005				
Category: Stucco		Location: Exterior	Description: Various exterior stucco fixes needed	Incomplete
Partner: Tri Valley Plastering & Drywall		Type:		
Code: J_028				
Category: Concrete		Location: Exterior	Description: Concrete splatter on stucco	Incomplete
Partner: Tri Valley Plastering & Drywall		Type:		