

All Defects		Lot 26/Tract 6260		
<div><div></div>Anlin Windows</div>				
Code: ZZ_259		Location:		
Category: Windows		Type:	Description: Master won't open	Incomplete
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_256		Location:		
Category: Cabinets		Type:	Description: Cabinet touch up kitchen	Incomplete
Partner: Cabinet Connection				
<div><div></div>Central Valley Rain Gutters</div>				
Code: ZZ_260		Location:		
Category: Rain Gutters		Type:	Description: Gutter down spout missing	Incomplete
Partner: Central Valley Rain Gutters				
<div><div></div>Elia Painting</div>				
Code: ZZ_255		Location:		
Category: Paint		Type:	Description: Paint all baseboards have bad tape lines	Incomplete
Partner: Elia Painting				
<div><div></div>Everlast Paint</div>				
Code: ZZ_258		Location:		
Category: Paint		Type:	Description: Paint crown in master	Incomplete
Partner: Everlast Paint				
<div><div></div>Tile Interiors</div>				
Code: ZZ_257		Location:		
Category: Tile		Type:	Description: Grout in entry hall	Incomplete
Partner: Tile Interiors				