## **De Young Properties**

Lot 357/Tract 0273	Items: 16	CH Items: 1	Checklist Inspections: 181
Cabinet Connection	on		
Code: ZZ_1101 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Touch up around fridge surround	Incomplete
Code: ZZ_1102 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Stain coming off on drawer right of oven	Incomplete
Code: ZZ_1103  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on door right of oven lower	Incomplete
Code: ZZ_1104  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on upper cabinet doors right of microwave	Incomplete
Code: ZZ_1105  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on door faces left of microwave	Incomplete
Code: ZZ_1106  Category: Cabinets  Partner: Cabinet  Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on doors left of oven lowers	Incomplete
Code: ZZ_1107  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinets have scratches, chips, and/or cracks	Description: Scratches on island doors under sink	Incomplete

Lot 357/Tract 0273	Items: 16	CH Items: 1	Checklist Inspections: 181
Code: ZZ_1108  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinet drawers and/or doors need to be adjusted	Description: Doors right now f oven are uneven	Incomplete
Code: ZZ_1109  Category: Cabinets  Partner: Cabinet Connection	Location: Kitchen  Type: Cabinet drawers and/or doors need to be adjusted	Description: Doors on island are uneven	Incomplete
Code: ZZ_1111  Category: Cabinets  Partner: Cabinet Connection	Location: Bathroom 1  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on drawer face	Incomplete
Code: ZZ_1112 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1  Type: Scratches/chips/cracks/gouges in cabinets	Description: Scratches on door faces left vanity	Incomplete
Elia Painting			
Code: ZZ_1114  Category: Paint  Partner: Elia  Painting	Location: Exterior  Type: Stucco pop-out, shutters and/or deco vents, or fascia paint issues	Description: Paint touch up on man door	Incomplete
Landscape Connec	ction		
Code: ZZ_1113  Category: Landscaping  Partner: Landscape Connection	Location: Exterior Type: Missing	Description: Missing grass	CRITICAL Incomplete
Ohanians Drywall			
Code: ZZ_1099  Category: Drywall  Partner: Ohanians Drywall	Location: Bathroom 2  Type: Drywall texture issues	Description: Drywall bubble by door casing	Incomplete

Checklist Lot 357/Tract 0273 Items: 16 CH Items: 1 Inspections: 18i Code: ZZ\_1100 Location: Entryway Description: Drywall Category: Drywall Incomplete crack by entry of bed 2 Type: Drywall texture issues Partner: Ohanians Drywall Simas Flooring & Design

Category: Carpet /

Hardwood / Laminate

Code: ZZ\_1110

Location: Bedroom 1

Type: Carpet is not installed

Partner: Simas Flooring & Design Description: Squeak under carpet pad

Incomplete