






All Defects		Lot 142/Tract 0273	
<div><div></div>Anlin Windows</div>			
Code: ZZ_2970	Location:	Description: Please adjust window in master bedroom is hard to open	Incomplete
Category: Windows	Type:		
Partner: Anlin Windows			
<div><div></div>Cabinet Connection</div>			
Code: ZZ_2965	Location:	Description: Clean interior of bath 2 cabinet Cabinet nick on top of cabinet door	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2968	Location:	Description: Touch up cabinets in kitchen Crown molding cut above fridge surround Touch up on cabinet face above fridge Touch up bottom panel face Scratches on drawer face left of sink Scratches across drawer faces to the right of oven Scratches on inside of upper cabinets to the right of oven Crown to the right of oven is cut and very noticeable	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2971	Location:	Description: Scratches on faces of drawers in master bathroom Pencil marks on cabinets	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
<div><div></div>Central Valley Overhead Door</div>			
Code: ZZ_2973	Location:	Description: Garage door opener’s are above motor	Incomplete
Category: Garage Door	Type:		
Partner: Central Valley Overhead Door			
<div><div></div>De Young Properties</div>			
Code: ZZ_2962	Location:	Description: Front pergola	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			
<div><div></div>Elia Painting</div>			

Code: ZZ_2963	Location:		
Category: Paint	Type:	Description: Paint front door	Incomplete
Partner: Elia Painting			
Code: ZZ_2964	Location:		
Category: Paint	Type:	Description: Finish painting baseboard in home	Incomplete
Partner: Elia Painting			
 Fresno Shower Door & Mirror			
Code: ZZ_2972	Location:		
Category: Shower Door & Mirror	Type:	Description: Missing mirrors in master bath Missing mirror in bath 2 Missing shower door in master bathroom	Incomplete
Partner: Fresno Shower Door & Mirror			
 Landscape Connection			
Code: ZZ_2974	Location:		
Category: Landscaping	Type:	Description: Fill gap at bottom Of fence around home	Incomplete
Partner: Landscape Connection			
 Ohanians Drywall			
Code: ZZ_2966	Location:		
Category: Drywall	Type:	Description: Drywall line in bed 2 approx 3 feet on left side of closet	Incomplete
Partner: Ohanians Drywall			
 Tri Valley Plastering & Drywall			
Code: ZZ_2961	Location:		
Category: Stucco	Type:	Description: Fog color at patches around home	Incomplete
Partner: Tri Valley Plastering & Drywall			
 Visalia Tile			

All Defects		Lot 142/Tract 0273	
Code: ZZ_2967			
Category: Tile	Location:	Description: Grout missing in coat closet	Incomplete
Partner: Visalia Tile	Type:		
<div><div></div>Westech</div>			
Code: ZZ_2969			
Category: Electrical	Location:	Description: Install electrical outlets on back wall of kitchen	Incomplete
Partner: Westech	Type:		
Code: ZZ_2969			
Category: Electrical	Location:	Description: Install electrical outlets on back wall of kitchen	Incomplete
Partner: Westech	Type:		