









All Defects		Lot 139/Tract 0273		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2772		Location:	Description: Missing twe in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2777		Location:	Description: Twe missing in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2778		Location:	Description: Scratches on trim by fridge surround	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2779		Location:	Description: Cabinet scratches on faces of doors and drawers in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2781		Location:	Description: Missing scribe on kitchen island	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2785		Location:	Description: Missing twe in master bathroom cabinet	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>De Young Properties</div>				
Code: ZZ_2773		Location:	Description: Scratch marks on tub in bath 2	Incomplete
Category: Builder Personnel		Type:		
Partner: De Young Properties				
<div><div></div>Elia Painting</div>				

Code: ZZ_2783			
Category: Paint	Location:	Description: Paint missing on baseboard in master bedroom	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_2784			
Category: Paint	Location:	Description: Dented baseboard in master closet	Incomplete
Partner: Elia Painting	Type:		
 Fenceworks			
Code: ZZ_2790			
Category: Fence	Location:	Description: Fence missing	Incomplete
Partner: Fenceworks	Type:		
 Landscape Connection			
Code: ZZ_2791			
Category: Landscaping	Location:	Description: Backyard irrigation missing	Incomplete
Partner: Landscape Connection	Type:		
 Matthews Quality Construction			
Code: ZZ_2775			
Category: Millwork	Location:	Description: Garage door does not auto close	Incomplete
Partner: Matthews Quality Construction	Type:		
 Quality Plumbing			
Code: ZZ_2776			
Category: Plumbing	Location:	Description: No hot water in bath 2	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_2780			
Category: Plumbing	Location:	Description: No hot water in kitchen	Incomplete
Partner: Quality Plumbing	Type:		

All Defects		Lot 139/Tract 0273		
Code: ZZ_2787		Location: Type:	Description: No hot water master bath	Incomplete
Category: Plumbing				
Partner: Quality Plumbing				
 Simas Flooring & Design				
Code: ZZ_2788		Location: Type:	Description: Blinds not installed	Incomplete
Category: Carpet / Hardwood / Laminate				
Partner: Simas Flooring & Design				
 Vega Cleanup				
Code: ZZ_2774		Location: Type:	Description: Clean clean clean	Incomplete
Category: Clean Up Interior				
Partner: Vega Cleanup				
Code: ZZ_2782		Location: Type:	Description: Clean clean clean the kitchen	Incomplete
Category: Clean Up Interior				
Partner: Vega Cleanup				
Code: ZZ_2786		Location: Type:	Description: Clean and remove all debris on cabinets in master bathroom	Incomplete
Category: Clean Up Interior				
Partner: Vega Cleanup				
 Visalia Tile				
Code: ZZ_2789		Location: Type:	Description: Grout missing by fridge surround	Incomplete
Category: Tile				
Partner: Visalia Tile				
 Westech				
Code: ZZ_2771		Location: Type:	Description: Missing plate cover in bed 3 for outlet	Incomplete
Category: Electrical				
Partner: Westech				