De Young Properties

Lot 152/Tract 0273	Items: 24	CH Items: 0	Checklist Inspections: 0
Cabinet Connection			
Code: ZZ_515 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Issues with cabinet drawers and/or doors functionality	Description: Doors not aligned	Incomplete
Code: ZZ_516 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Issues with cabinet drawers and/or doors functionality	Description: Door knob of left doo scratched	Incomplete
Code: ZZ_519 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Drawer in center of vanity misaligned	Incomplete
Code: ZZ_521 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Twe missing	Incomplete
Code: ZZ_522 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Issues with cabinet drawers and/or doors functionality	Description: Twe missing	Incomplete
Code: ZZ_523 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Adjust drawer to the right of oven	Incomplete
Code: ZZ_524 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Adjust drawer to the left of oven	Incomplete

Lot 152/Tract 0273	Items: 24	CH Items: 0	Checklist Inspections: 0
Code: ZZ_525 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Twe not installed in kitchen	Incomplete
Code: ZZ_526 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Adjust upper cabinet doors to the left of microwave not aligned	Incomplete
Code: ZZ_527 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinet drawers and/or doors need to be adjusted	Description: Nail holes showing on side panel of island	Incomplete
Central Distributing			
Code: ZZ_530 Category: Fireplace Unit Partner: Central Distributing	Location: Great Room Type: Missing parts or all parts not installed	Description: Not started up	Incomplete
Granite Mountain Stor	ne Design		
Code: ZZ_532 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Kitchen Type: Caulk at countertop and/or backsplash has a crack or is missing	Description: Counter top not installed	Incomplete
John Ventresca Co			
Code: ZZ_529 Category: Fireplace Surround Partner: John Ventresca Co	Location: Great Room Type: Mortar has cracks or is missing in areas	Description: Not installed	Incomplete
MV Style Electric			

Lot 152/Tract 0273	Items: 24	CH Items: 0	Checklist Inspections: 0
Code: ZZ_534 Category: Electrical Partner: MV Style Electric	Location: Great Room Type: Light switch cover and outlet cover not flush	Description: Plate covers are crooked	Incomplete
Matthews Quality Con	struction		
Code: ZZ_531 Category: Millwork Partner: Matthews Quality Construction	Location: Great Room Type: Baseboards missing or have chips/gouges	Description: Baseboard not installed	Incomplete
Ohanians Drywall			
Code: ZZ_514 Category: Drywall Partner: Ohanians Drywall	Location: Bedroom 3 Type: Drywall has crack, gash, hole, and/or gouge	Description: Excess drywall in corner of bed 3 Drywall gash on wall in bed 3	Incomplete
Code: ZZ_528 Category: Drywall Partner: Ohanians Drywall	Location: Great Room Type: Drywall texture issues	Description: Drywall repair in great room	Incomplete
Code: ZZ_533 Category: Drywall Partner: Ohanians Drywall	Location: Dining Nook Type: Drywall has crack, gash, hole, and/or gouge	Description: Drywall ding in dining room	Incomplete
Quality Plumbing			
Code: ZZ_518 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type: Defect(s) in Bath/Shower fitter/surround	Description: Scratches on tub	Incomplete
Code: ZZ_520 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type: Fixture not installed correctly	Description: Left faucet scratched	Incomplete

Lot 152/Tract 0273	Items: 24	CH Items: 0	Checklist Inspections: 0
Code: ZZ_536 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Stucco fog around home	Incomplete
Code: ZZ_537 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Dent in stucco in backyard	Incomplete
True Frame			
Code: ZZ_535 Category: Framing Partner: True Frame	Location: Exterior Type: Fascia, wood railing, siding, columns, or any other exterior wood product missing or damaged	Description: Wood siding cracked on right side of garage door	Incomplete
Visalia Tile			
Code: ZZ_517 Category: Tile Partner: Visalia Tile	Location: Bathroom 2 Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Grout crack by tub	Incomplete